

Schuylkill River Development Corporation


Conceptual Design Services for Grays Ferry Pedestrian Bridge, Philadelphia, PA Project No. GFP-1

Concept Studies Report



Grays Ferry Pedestrian Bridge over The Schuylkill River

PREPARED BY:






Schuylkill River Development Corporation

Conceptual Design Services for Grays Ferry Pedestrian Bridge, Philadelphia, PA Project No. GFP-1

Concept Studies Report




Grays Ferry Pedestrian Bridge

over

The Schuylkill River

PREPARED BY:






TABLE OF CONTENTS

I. INTRODUCTI	ION	1
II. EXISTING ST	TRUCTURE	2
III. RIGHT OF V	WAY & EXISTING PROPERTIES WITHIN THE PROJECT SITE	3
IV. PERMITS		4
V. VERTICAL O	CLEARANCE REQUIREMENTS	6
VI. VERTICAL	PROFILE & HORIZONTAL ALIGNMENT	8
VII. PROPOSED	O CONCEPTS	8
TRUSS CON TRUSS CON CABLE-STA CABLE-STA	NCEPT 1 NCEPT 2 NCEPT 3 AY CONCEPT 1 AY CONCEPT 2 AY CONCEPT 3	9 10 10
VIII. COST EST	TIMATES	12
IX. PUBLIC INV	VOLVEMENT	13
X. RECOMMEN	NDATION	14
XI. ACKNOWLI	EDGEMENTS	15
	Existing Plans	
	Conceptual Plans	
	Quantity and Estimate Calculations	
ADDENDIA D.	Roadway Plane	

APPENDIX D: Roadway Plans

APPENDIX E: Project Site Photographs

APPENDIX F: Public Involvement **APPENDIX G:** Inspection Report

I. Introduction

A conceptual design study has been performed for a proposed pedestrian bridge adjacent to the existing Grays Ferry Avenue highway bridge over the Schuylkill River. The proposed bridge, which is in the location of the abandoned Conrail swing bridge, will serve as a key connection in the Schuylkill Banks trail. The Schuylkill Banks trail stretches between the Art Museum and Locust Street, and there are several sections under design south of Locust Street. The ultimate goal of the Schuylkill River Development Corporation (SRDC) is for the trail to continue down the east bank of the river to Grays Ferry and then cross over to the west bank to enable a connection to Historic Bartram's Garden and ultimately to Fort Mifflin. This crossing is envisioned near the south end of the DuPont Crescent in the vicinity of Grays Ferry Avenue. The DuPont Crescent is a recently enhanced trail area that follows along the Schuylkill banks from 34th Street down to Grays Ferry Avenue (See Figure 1 below).




Figure 1: Project Location Map

This report presents the conceptual study done for providing a new pedestrian and bicycle facility to cross the river at the existing Conrail Bridge location. Six different structural concepts are presented as a means of traversing the river. Some concepts involve reusing the existing abandoned Conrail Bridge in conjunction with portions of new structure, while others involve completely new structures passing over the existing truss that would possibly be rehabilitated and serve as a historic "relic" of the past. Advantages and disadvantages of each concept are provided. The report concludes with a preliminary cost estimate for each concept.

II. Existing Structure

The existing structure, which was built in 1901, consists of four spans over the Schuylkill River. Each 97'-9 3/8" approach span is made-up of two 8'-6" deep steel plate girders. The existing 226'-3" long swing steel truss is currently supported in the open position at mid-span with two equal cantilever spans. The bridge carried one non-electrified freight line. The truss is permanently in open position since the structure and rail line were abandoned by its owners. It is very likely that the mechanical systems do not function anymore. Additional information may be found in the existing plans (See Appendix A).

An in-depth inspection was conducted between June 21 and June 23, 2011, and determined that the overall condition of the bridge was fair to poor. The structural integrity of the superstructure has not been compromised; however, the extent of steel repairs needed to extend the life of the structure will be costly. The superstructure steel had many areas of severe deterioration below the deck rails, particularly in bottom chords, gusset plates, and lateral bracing. The substructure stone abutments and piers had minimal areas of concern. The concrete retaining wall at the north end of the East Approach had several areas of deteriorated and spalled concrete. The paint system has failed throughout the entire superstructure with moderate to severe surface rust typical.

Based on engineering judgment and the fact that the original purpose of this bridge was to carry the Cooper E80 train live load, the existing structure with appropriate repairs should have more than sufficient capacity to carry pedestrian loads. Once the preferred concept has been identified a detailed analysis on existing structures that will be reused will be carried out and necessary repair details will be developed.

AWK Engineers provided survey information in the river bed in order to determine if there is any concern for scour and undermining of the substructure foundations. A section of the river bed created from the survey is shown on the General Plan and Elevation (See Appendix B). Further investigation of the existing substructure, consisting of underwater inspection, will take place in post conceptual design phases.

III. Right of Way & Existing Properties within the Project Site

Field survey of the project area was performed by AWK in November, 2009. Vertical control was in accordance with NAVD 1988. Digital Terrain Model (DTM) for the survey has been produced and is reflected in all of the conceptual General Plans. A property owner mosaic has also been created on the project base plan shown in the General Plans for each of the concepts.

As shown on the plans in Appendix B, the existing truss lies in the ownership right-of-way of Conrail Shared Assets. The width of required right-of-way in the trail areas for the trail and greenway is 60 feet wide. The width of required right-of-way in the area of the bridge is increased to an 80 foot width in order to accommodate substructures and embankment areas. There is a 100 ft x 100 ft temporary construction easement required on the west bank for construction staging or crane operation. There is also a 50 ft x 250 ft temporary construction easement potentially required if the contractor chooses to rehabilitate the truss on land. Required right-of-way and temporary easement lines are shown in the roadway plans located in Appendix D. The following table summarizes the approximate acreage of required permanent and temporary land acquisition based on the current alignment.

REQUIRED RIGHT-OF-WAY

Owner (Property Mosaic)	SF of Required R.O.W.	Acres of Required R.O.W.
PHILADELPHIA AUTHORITY FOR INDUSTRIAL DEVELOPMENT EXHIBIT A-1 INSTR 51609928	929	0.0213
PARCEL NUMBER THREE D-1081-431	3031	0.0696
NEW YORK CENTRAL LINES LLC PURPORTED TO BE OWNED BY CSX TRANSPORTATION, INC.	88818	2.0390
REDEVELOPMENT AUTHORITY OF THE CITY OF PHILADELPHIA	31904	0.7324
AERO PHIL FE, LLC	14526	0.3335

TEMPORARY CONSTRUCTION EASEMENTS

Owner (Property Mosaic)	SF of Required R.O.W.	Acres of Required R.O.W.
NEW YORK CENTRAL LINES LLC PURPORTED TO BE OWNED BY CSX TRANSPORTATION, INC.	16090	0.3694

From station 0+00 to station 6+00, the required right-of-way cannot be obtained due to overlap with existing CSX railroad tracks and drainage ditch. Either a smaller trail and right-of-way footprint or refined alignments to gain access to Bartram's Gardens can be investigated during property acquisition phase of the project.

IV. Permits

Potential permits needed for the Grays Ferry Bridge over the Schuylkill River project include: a DEP Joint Application Form which covers the Pennsylvania Water Obstruction and Encroachment Permit and the U.S. Army Corps Section 404 Permit; a letter to DEP for Coastal Zone Management Consistency as the project lies within Pennsylvania's Delaware Estuary Coastal Zone; and a US Coast Guard Bridge Permit for navigable waters. A general NPDES permit will also be necessary if more than 1 acre of disturbance will occur during project construction. If less than 1 acre of disturbance occurs, the NPDES permit is not required. An E&S Plan Review will still be required even if a NPDES permit is not. A Conditional Letter of Map Revision (CLOMAR) will be required for FEMA if there is any change in elevation to the floodplain by the proposed project.

All permits should be pulled together concurrently with the design phase of the proposed project. Permits should be submitted in the semi-Final/Final Design Phase. Insignificant changes made to the plans after submission of the permits can be submitted in a modification package.

DEP Joint Application Form

The DEP Joint Application Form is for the Pennsylvania Chapter 105 and 106 Water Obstruction and Encroachment and Permit and U.S. Army Corps of Engineers Section 404 Permit. The DEP has state and federal authorization for the proposed project unless it is determined that the application does not fall under dual review by the DEP it will be forwarded to the Corps for federal review. The permit requires the completion of an Environmental Assessment Form, General Information Form (GIF), hydrologic and hydraulic analysis, E&S control plan and approval letter, the determination of historic/archaeological site presence from PHMC, completed and approved Pennsylvania Natural Diversity Inventory Form and site plans including cross sections and profiles. A Pre-Application Conference is recommended but is not required for the application process. Once the application is submitted, it is expected to take 6 – 9 months for review.

Army Corps of Engineers Permit

The Army Corps of Engineers Permit informs the Corps what the proposed project entails. General information is needed to fill out this form such as the location and purpose of the project as well as if fill material is to be discharged. This permit must be sent in separately from the DEP Joint Permit because this project involves the Schuylkill River. Review of this permit is expected to take between 30 and 90 days.

Nationwide Permit No. 15 U.S. Coast Guard Approved Bridges may also be required from the Corps in order to regulate fill in the waters as a result of the proposed project. Nationwide permits are issued for projects with minimal impacts with as little delay or paperwork as possible.

US Coast Guard Bridge Application Permit

The Schuylkill River is a navigable waterway; therefore a Bridge Permit Application with the US Coast Guard is required. Information needed to complete this permit includes: the primary authority for the construction of the bridge and under what legislative authority the bridge is being built, proposed clearances and elevations, owner and type of existing bridge structure at the site, construction activity, and environmental effects. State and local authorizations are also required, as well as information about fill, if applicable. Adjacent property owners within a half mile radius are also needed. The estimated cost of the project and estimated total value of yearly commercial shipping on the waterway affected by the bridge is also required. Lastly, drawings of the proposed project must be submitted in the application. The Coast Guard also requires navigational lights on bridges that cross waterways, temporary lights during construction and permanent lighting post-construction.

It should be expected to require about 3 months to pull the application together and another 6-9 months for the Coast Guard to review the application. At least one Pre-Application Conference will be needed; one before the application is submitted and possibly one during application review. One meeting can be held with all of the regulating agencies together instead of multiple separate meetings.

NPDES Permit

A general NPDES permit will be required if more than 1 acre of disturbance will result from the proposed project. Information needed for the permit includes general project information (description, location, and existing land use), fill materials, total disturbed area, and estimation timeframe for project completion. E & S Plans must also be submitted in the application even if less than 1 acre will be disturbed. The design team should also note that a post-construction storm water management plan will also need to be developed. It should be expected to take 30 – 90 days for the application review.

Coastal Zone Management Consistency

The letter to DEP for Coastal Zone Management Consistency is necessary because the project lies within Pennsylvania's Delaware Estuary Coastal Zone. This letter should include general information about the proposed project. DEP will review the letter and decide if the project meets the coastal zone requirements. Response time from DEP for this letter is expected to be between 30 and 90 days.

CLOMAR

A Conditional Letter of Map Revision may be required for FEMA if there is any elevation change to the floodplain by the proposed project. The letter will indicate if the project, if built as proposed, will be recognized by FEMA. Once a project has been completed, the community

must request a revision to the Flood Insurance Rate Map (FIRM) to reflect the project. Approval from FEMA may take up to one year so it is highly recommended to avoid changing floodplain elevation.

Mitigation

The regulating agencies require that permitted activities resulting in impacts to the project area require mitigation. It is not anticipated that this project will require any mitigation as impacts will be minimal.

NOTE: If this project is state or federally funded, an environmental document will need to be prepared.

V. Vertical Clearance Requirements

The adjacent Grays Ferry Avenue Bridge has a 50 foot vertical clearance. In addition, the I-76 Bridge also has a 50 foot vertical clearance. These are the two fixed span structures between the project site and the remaining industrial site upstream, Trigen Energy. The upstream University Avenue structure is a lift bridge. It was anticipated that due to limited amount of navigable traffic, the vertical clearance may be able to be reduced for this section of the Schuylkill River. Therefore, a 35 foot clearance was evaluated.

A 35 foot vertical clearance is preferable for pedestrians and bicyclists since it would provide a less strenuous, shorter travel time and more direct crossing over the river. A lower vertical clearance was also preferable to the owner since it would limit costs. A 35 foot clearance option would produce a more aesthetically pleasing structure for any concept, particularly those that reused the existing truss.

Initial contact with US Coast Guard representative, Terry Knowles, was made in August 2009 to discuss permitting. Due to the proposed structure's location over a navigable water way, the US Coast Guard permit will be required. However, the permitting process will become more lengthy and involved if we were to propose a vertical clearance that is less than the existing adjacent Grays Ferry Avenue Bridge's. According to the National Oceanic and Atmospheric Administration (NOAA) nautical charts, the Grays Ferry Avenue Bridge provides a 50 foot vertical clearance (See Figure 2 below).




Figure 2: NOAA Nautical Chart in the Vicinity of Grays Ferry Avenue

Further investigation was done in order to determine if the 50 foot clearance definitely had to be met based on the operations and current demands on the river in the vicinity of the bridge. We verified there is only one operation that would be affected by vertical clearances for the proposed structure, which is an oil shipment to Trigen Energy. The Trigen Energy facility is located about one mile north on the river from the project site (See Figure 1).

We established contact with Trigen Energy through Pat Davin. Pat informed us that the oil shipped to Trigen is used to supply steam power to the downtown Philadelphia area, including many of the large hospitals. Frequency of the oil shipments varies from about 12 to 30 times a year and will definitely be a consistent power source in the future. Pat also stated that the PECO facility, which is located adjacent to the Trigen facility, operates strictly from the oil that comes from Trigen.

We attempted coordination of our initial concepts with Vane Brothers Towing, which is the company responsible for towing the barges of oil to the Trigen facility. According to a Vane Brothers representative, they have two different boats available for the operation. One boat requires a 40 foot clearance and the other a 49 foot clearance. Vane Brothers stated that they cannot be limited to using just one of the boats. Therefore, the required minimum vertical clearance based on the current boat traffic will be set at 50 feet.

The existing vertical clearance between mean high water and truss bottom chord is 16.77 feet. In order to reuse the truss in the open position, it would have to be raised 33.23 feet above its current location.

VI. Vertical Profile & Horizontal Alignment

The vertical profile in the area of the bridge was set to maintain a 50 foot minimum vertical clearance above mean high water in the navigable channel. The profile design criteria were based on FHWA publication for *Designing Sidewalks and Trails for Access*. The FHWA outdoor facility guidance allows a 1:12 slope to be used for up to 200 feet without landings. Therefore, the profile was set to a 1:12 slope from the existing piers to the proposed abutments. The resting interval at the abutment shall be 5 foot minimum in length with a slope no greater than 2.0% based on FHWA requirements. From the abutment landing the profile is sloped at 1:12 until it ties into existing ground elevation. From the existing ground tie-in, the profile will match existing ground terrain with a slope no greater than 1:20.

The proposed horizontal alignment was primarily determined by existing features. The alignment begins at the southeast end of the project site at the tie-in to 49th street. From there the alignment follows the path of an existing gravel drive. The alignment deviates from tangent between station 1+50 and station 3+00 in order to avoid an abandoned building. The alignment continues along the existing gravel drive from station 3+00 to station 11+00. The alignment then shifts to follow the existing abandoned railroad alignment. The alignment continues along this path over the Schuylkill River to the east bank, where a tie-in to the Dupont Crescent will occur near Grays Ferry Avenue.

VII. Proposed Concepts

The refining of the proposed concepts has been a dynamic process between the engineers, architects and owner. There were initial concepts created by Agoos/Lovera Architects assuming a 35 foot vertical clearance. Once the required vertical clearance of 50 feet was verified, some of the original concepts were eliminated. With the elimination of initial concepts, new concepts were added for a final number of six different concepts proposed at the end of the conceptual design phase. Two of the proposed concepts incorporate reuse of the existing truss in conjunction with either a prefabricated truss or a cable-stay structure. The other four concepts entail leaving the existing truss in place and constructing completely new structures that pass over the existing truss. Two of the four concepts that pass over the existing truss consist of prefabricated trusses and the other two consist of cable-stay structures.

There are some elements that are consistent for all six concepts. All concepts assume a proposed concrete stub abutment supported on steel piles. Embankment would have to be provided at each abutment location. All concepts assume a proposed fender system. However, the required size of the fender system varies among concepts. Every concept will also include a pedestrian railing and bridge lighting. Very cursory design calculations have been done for some elements of the

concepts just for cost purposes. Therefore, member dimensions, sizes or shapes shown will be refined in future design stages.

The following will give a brief description of each concept that is being considered for the next stage of design, along with advantages and disadvantages. Refer to General Plan and Elevations of each concept located in Appendix B for visual representation.

Truss Concept 1

This concept consists of a prefabricated Contech "link" style truss system. The proposed truss passes over the existing truss with a support through the truss at the existing center pier. The trusses are also supported at the existing east and west pier locations and at new abutment locations. Piers are assumed to be made of reinforced concrete for cost estimate purposes only. The two center spans are 113'-1 ½" and the two approach spans are 140'-0". Approximate required truss depth, based on span configuration, is 14'-0".

Advantages of this concept are:

- Prefabricated truss elements provide quick installation and reduced site preparation time
- Minimal maintenance
- Relatively low cost

Disadvantages of this concept are:

- Construction of new center pier may require removing and reinstalling existing truss
- Requires a large fender system to protect the existing truss and boaters

Truss Concept 2

This prefabricated Contech "keystone" style truss option offers a bit more flare than Truss Concept 1 with the parabolic shape trusses. The main span of the proposed truss spans completely over the existing truss between the existing east and west piers. The main span is 226'-3". The approach spans, consisting of smaller "keystone" style prefabricated trusses, span from the existing east and west piers to new east and west abutments, respectively. The approach spans are each 140'-0". The deepest portion of the main span varying depth truss is 23'-0". The deepest portion of the approach span trusses is 15'-0". The two proposed piers are assumed to be concrete.

Advantages of this concept are:

- Prefabricated truss elements provide quick installation and reduced site preparation time
- Minimal maintenance
- Relatively low cost
- Leaves the option of removing and reinstalling the existing truss up to the contractor since there is not a proposed center pier.

Disadvantages of this concept are:

• Requires a large fender system to protect the existing truss and boaters

Truss Concept 3

This concept incorporates the reuse of the existing Conrail truss in the closed position (truss is longitudinal to trail baseline). The existing truss is raised to provide 50 foot vertical clearance between bottom chord and mean high water elevation. The existing 226'-3" long truss would be supported by new pier extensions at the center pier and the east and west piers, creating two equal spans of 113'-1 ½". The pier extensions are assumed to be concrete. The 140'-0" approach spans consist of single-span prefabricated Contech "connector" style trusses. The approach spans are supported at the east and west piers and the east and west abutments, respectively. The superstructure consists of a composite concrete deck.

Advantages of this concept are:

- Reuses a historic element and gives it prominence in the new structure
- Reduces cost by efficiently incorporating the existing rehabilitated truss into the structure
- Lowest cost option
- Reduced size of required fender system due to smaller obstruction in the navigable channel

Disadvantages of this concept are:

- The existing truss is not very aesthetically pleasing when combined with smaller span & shallower trusses of a different type and when it is raised up to this elevation.
- There would be additional and possibly complicated labor associated with jacking the very large existing truss to the required elevation.
- Significant repairs need to be made to the truss in order to safely carry pedestrian and bicyclist loads.

Cable-Stay Concept 1

This concept also incorporates the reuse of the existing Conrail truss in the closed position, similar to truss concept 3. However, the approach spans are comprised of double mast "fan" type cable-stay structures. Cable-stay concept 1 is thought to be a "hybrid" structure that combines a very old structure with a very new structure. The masts are assumed to be steel and supported on the existing abutment. Each cable-stay portion of the structure is 163'-6" based on location of existing piers and abutments and proposed abutment. The back span from mast to proposed abutment is 65'-8 5/8" and the front span from mast to pier is 97'-9 3/8". The superstructure is a girder and floorbeam system with a composite concrete deck. The approximate floorbeam spacing and cable-stay spacing at deck level is assumed to be 20'-0"

A decision would have to be made if it is more efficient and cost effective to account for the shorter span in the mast design, to balance the spans with a large concrete counterweight or to extend the length of the structure to create equal spans. Although the original loads the bridge was designed for far exceed what the current proposed loads are, it is questionable if the existing abutment is sufficient to take all the additional compressive reaction from the masts. Further analysis can verify the adequacy of the existing abutment for this load.

Advantages of this concept are:

- Reuses a historic element and gives it prominence in the new structure
- Reduces cost by efficiently incorporating the existing rehabilitated truss into the structure
- Relatively low cost among the cable-stay structures
- Reduced size of required fender system due to smaller obstruction in the navigable channel
- The cable stay portion of the structure has many aesthetic qualities

Disadvantages of this concept are:

- The existing truss is not very aesthetically pleasing raised up to this elevation, particularly when combined with a radically different type of superstructure.
- There would be additional and possibly complicated labor associated with jacking the very large existing truss to the required elevation
- Significant repairs need to be made to the truss in order to safely carry pedestrian and bicyclist loads.
- Requires contractors specialized in cable-stayed bridge construction that may not be readily available in the region.

Cable-Stay Concept 2

This concept is the most striking concept aesthetically. The prominent feature of this structure is the continuous steel mast that supports the cable stays while providing unity and symmetry. The portions of the mast that rise above the structure are rectangular hollow steel tapered tube sections. The steel support at each pier and abutment is a rectangular hollow steel section with a constant width and depth. The superstructure is a stringer floorbeam system with a composite concrete deck. The approximate floorbeam spacing and cable-stay spacing at deck level is assumed to be 20'-0".

Advantages of this concept are:

- Has many aesthetic qualities
- Contrasts with the existing structure while providing unity and symmetry in design
- Has a unique shape that will attract users and visitors

Disadvantages of this structure are:

- Highest cost option
- Requires contractors that specialize in cable-stay construction that may not be readily available in the region
- Requires a large fender system to protect the existing truss and boaters

Cable-Stay Concept 3

This style of this concept is similar to cable-stay concept 3. However, in this case the main spans consist of cable-stay supported structure that passes over the existing truss in its current open position. The cable pairs are configured in a harp pattern and are supported by two double-mast steel pylons. The proposed pylons are situated on the existing west and east piers, creating a

main span equal to 226'-3". The steel pylons are made of hollow steel boxes. The approach span supports are located at existing west and east abutments, which creates cable supported back spans equal to 97'-9 3/8". The 65'-8 5/8" approach spans are assumed to be comprised of prefabricated Contech trusses for cost purposes. However, there are numerous other superstructure types that could support that span length. The proposed east and west piers are 3'x14' solid concrete piers supported at existing east and west abutment locations, respectively.

Advantages of this concept are:

- The structure is a very aesthetically pleasing modern structure with clean lines that would attract users and the public
- The concept provides passing completely over the existing truss so there the involved operation of lifting the existing truss to a higher vertical clearance would not be required

Disadvantages of this concept are:

- Requires contractors that specialize in cable-stay construction that may not be readily available in the region
- There is a relatively high cost, however, not as high as cable-stay concept 2
- Requires a large fender system to protect the existing truss and boaters

VIII. Cost Estimates

The table below shows a summary of the cost estimates for all six structure alternates. Detailed cost estimates and calculations are given in Appendix C. The cost estimate is preliminary and includes a contingency to cover costs that cannot be determined without a more detailed design. There is a 15% contingency built into the truss options and a 20% contingency built into the cable-stay options. The reason for the difference in the contingencies is the trusses are a preengineered product that we received pricing from a fabricator that has a good handle on the required structure to meet the needs. The cable-stay concepts include a higher contingency because the design has not been engineered to as full of an extent as the trusses and is only based on rough calculations.

Structure Cost Estimates					
Concept Estimated Cost					
Truss Concept 1	\$ 4,601,755				
Truss Concept 2	\$ 4,629,896				
Truss Concept 3	\$ 3,496,651				
Cable-Stay Concept 1	\$ 4,801,213				
Cable-Stay Concept 2	\$ 6,398,132				
Cable-Stay Concept 3	\$ 5,262,544				

The above cost estimate does not include the cost of the trail portions off the structure. The recent Dupont Crescent trail project, which consisted of 14 foot wide trails throughout the majority of the project site, received a low bid of \$1,723,544. The low bid cost without including any trees or planting was \$1,444,398. There was approximately 4,474 feet of trail associated with the Dupont Crescent project, which yields a cost of about \$333 per linear foot of trail. The trails in the vicinity of the Grays Ferry pedestrian bridge will be of a similar nature, with the exception of the large turf areas with extensive greenery constructed in the Dupont Crescent. There is approximately 1669 feet of asphalt trail proposed for this project. Based on the aforementioned bid price without planting and not including a contingency, the approximate cost for the trail portion of this project is \$555,777. The following table represents total project cost estimates.

The cost estimates do not include the cost of right-of-way acquisition, utility relocation, railroad agreements, or construction management and inspection services. The cost estimates use current pricing and do not account for inflation.

Total Project Cost Estimates					
Concept Estimated Cost					
Truss Concept 1	\$ 5,157,532				
Truss Concept 2	\$ 5,185,673				
Truss Concept 3	\$ 4,052,428				
Cable-Stay Concept 1	\$ 5,356,990				
Cable-Stay Concept 2	\$ 6,953,909				
Cable-Stay Concept 3	\$ 5,818,321				

IX. Public Involvement

Two stakeholder meetings were conducted to solicit public participation within the project development process. These meetings involved representatives of Bartram Gardens, Philadelphia Trolley Works, Delaware Valley Regional Planning Commission (DVRPC), City of Philadelphia Commerce Department, Philadelphia City Planning Commission, Schuylkill River Park Alliance (SRPA), Bicycle Coalition, and Southwest Community Development Corporation (SWCDC) and took place as follows:

- Stakeholder Committee Meeting #1: Nov. 12, 2009– 1:30 to 3:00 Philadelphia Trolley Works, Philadelphia, PA
- Stakeholder Committee Meeting #2: Sept. 09, 2010–10:00 to 12:00 held at the Philadelphia Trolley Works, Philadelphia, PA.

The minutes of these meetings are presented in Appendix F.

The first stakeholders meeting discussed various ways of achieving the crossing to provide a connection between the DuPont Crescent which is in design on the east side of the river and Bartram Gardens on the west side of the river. One suggested method was to build a swing bridge. The issue of clearance over the river at the suggested crossing was discussed. Before the required vertical clearance could be determined the designers needed to obtain additional information from the Coast Guard and the Trigen Energy, the main generator of boat traffic in this area.

During the second stakeholders meeting, the group requested a follow-up to the swing bridge concept. Joe Syrnick stated that he did not feel the City of Philadelphia would want to absorb the cost to operate and maintain a swing bridge. The group requested an official response from the City on this matter. The design team provided an update of the vertical clearance over the river. They reported that the Coast Guards and boat traffic in the area require a 50 ft clearance. Various structural concepts were presented by the design team and the attendees were able to narrow down the choice to Truss Concept #3.

As a follow up to the second meeting the SRDC wrote a letter and met with the City to discuss the possibility of providing a swing bridge at this location. The letter and the response are in Appendix F.

Additionally, a generally advertised public meeting (Public Open House) was held on Wednesday February 8, 2012 at the University Museum, of the University of Pennsylvania, 3260 South Street, Philadelphia. This public meeting was attended by 82 people who, following the presentation of the study and recommendation, were given the opportunity to ask questions and offer input. In general, there was a great support for the project. A copy of the flyer announcing this meeting is included in Appendix F.

X. Recommendation

Six different concepts were investigated and presented in this report. They are all feasible but each has different aesthetic qualities and carries a different cost. The results of the stakeholders meetings narrowed the number of concepts to one concept which is Truss Concept #3 (Option3). The opinion of the stakeholders was in line with that of the design team and the SRDC. Therefore, Truss Concept 3 with a cost of \$4,052,428.00 (option 3) will be carried through preliminary and final design.

XI. Acknowledgements

The Schuylkill River Development Corporation (SRDC) acknowledges the assistance provided by its project partners including members of the Project Study Committee. They are as follows:

Cynthia Dunlap PA Department of Conservation and

Natural Resources

Jon Edelstein Brownfields Manager

City of Philadelphia

Deborah Schaaf Senior Planning

Philadelphia City Planning Commission

Louise Turan Executive Director

Bartram's Garden

Sarah Clark Stuart Schuylkill River Park Alliance

Donna Henry Executive Director

Southwest CDC

Michael Kates Vice President

Philadelphia Trolley Works

Karen Cilurso Senior Regional Planner

DVRPC

Lane Fike Director of Capital Programs

SRDC

Joseph Sullivan, PE Project Manager

Consultant Study Team


Joseph Syrnick SRDC President


Additionally, this project is financed in part by a grant from the Community Partnerships Program, Environmental Stewardship Fund, under the administration of the Pennsylvania Department of Conservation and Natural Resources, Bureau of Recreation and Conservation and in part by the William Penn Foundation using a Take Me to the River Grant administered by the Delaware Valley Regional Planning Commission.

SRDC is indebted to these project partners without whom this project could not have been completed.

APPENDIX A


(Existing Plans)








APPENDIX B


(Conceptual Plans)

















APPENDIX C

(Quantity and Estimate Calculations)

& WHITNE

Project: Grays Ferry Ave Ped Bridge

Subject: Summary of Preliminary Cost Estimates

Designed by: AL


Date: July 8, 2010

Index No:

Job No: 3061


Date:

Checked by:




DATUM -75.00


\$4,601,755




\$4,629,896




\$3,496,651



\$6,398,132







Project: Grays Ferry Ave Ped Bridge

Subject: Truss Concept-1 Preliminary Cost Estimate

Designed by: NER

Date: May 19, 2010

Index No:

Job No: 3061

Checked by:

Date: 7

9/29/11

TRUSS CONCEPT - 1 COST ESTIMATE

New 2-Span Prefabricated Truss passing over existing rehabilitated truss

0204-0100 Class 3 Excavation CY 121 \$45.00 \$ 5,445 0205-0100 Foreign Borrow Excavation CY 7920 \$15.00 \$ 118,800 1001-0001 Class A Concrete (Piers and Abutments) CY 233 \$650.00 \$ 151,450 1001-0000 Class A AA Concrete (Deck) CY 127 \$1,100.00 \$ 139,700 1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 44070 \$1.71 \$ 75,360 1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$ 3,960 1018-0050 Removal of Existing Bridge LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.0 \$ 20,000 9000-0001 Bridge Lighting EA 4 40 \$500.00 \$ 20,000 900-0002 Replace Fender System LS 1 \$853,153.72 \$ 853,154	<u>Item No.</u>	<u>Item</u>	<u>Unit</u>	Ouantity	Unit Price	Cost
0205-0100 Foreign Borrow Excavation CY 7920 \$15.00 \$118,800 1001-0001 Class A Concrete (Piers and Abutments) CY 233 \$650.00 \$151,450 1001-0000 Class AAA Concrete (Deck) CY 127 \$1,100.00 \$139,700 1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 44070 \$1.71 \$75,360 1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$3,960 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Removal and Reinstall Existing Truss LS 1 \$236,000.00 \$227,500	0204-0100	Class 3 Excavation	CY			\$
1001-0001 Class A Concrete (Piers and Abutments) CY 233 \$650.00 \$ 151,450 1001-0000 Class AAA Concrete (Deck) CY 127 \$1,100.00 \$ 139,700 1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 44070 \$1.71 \$ 75,360 1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$ 3,960 1005-0143 HP 12x53 Steel Piles LS 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$ 853,154 9000-0004 Removal and Reinstall Existing Truss LS 1 \$236,000.00 \$ 227,500 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$	0205-0100	Foreign Borrow Excavation	CY	7920	\$15.00	\$
1001-0000 Class AAA Concrete (Deck) CY 127 \$1,100.00 \$ 139,700 1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 44070 \$1.71 \$ 75,360 1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$ 3,960 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.0 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$ 853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.0 \$ 227,500 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 900-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 <td< td=""><td>1001-0001</td><td>Class A Concrete (Piers and Abutments)</td><td>CY</td><td>233</td><td></td><td>\$ </td></td<>	1001-0001	Class A Concrete (Piers and Abutments)	CY	233		\$
Reinforcement Bars, Epoxy Coated (Deck)	1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$
1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 44070 \$1.71 \$75,360 1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$3,960 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 \$227,500 \$000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$803,700.00 \$803,700 \$900-0007 Contech Truss LS 1 \$803,700.00 \$803,700 \$900-0010 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 \$9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 \$9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 \$9075-0002 Containment SF 62230 \$3.00 \$186,690 \$9075-0002 Containment SF 62230 \$3.00 \$186,690 \$9075-0002 Containment Containment CS CS CS CS CS CS CS C	1002-0053	Reinforcement Bars, Epoxy Coated (Deck)	LBS	25400		\$
1003-0008 Dowel Holes, 16" Depth EA 132 \$30.00 \$3,960 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9008-0001 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9	1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	44070	\$1.71	\$
1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$ 853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$ 40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$ 803,700 9018-0001 Miscellaneous Steel Repairs LS 1 \$100,000.00 \$ 100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230	1003-0008	Dowel Holes, 16" Depth	EA	132		\$
1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9008-0001 Miscellaneous Steel Repairs LS 1 \$800,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF </td <td>1005-1143</td> <td>HP 12x53 Steel Piles</td> <td>LF</td> <td>400</td> <td>\$91.20</td> <td>\$</td>	1005-1143	HP 12x53 Steel Piles	LF	400	\$91.20	\$
9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9008-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9075-0002 Disposal of Bridge Waste SF 62230 \$3.00 \$186,690	1018-0050		LS	1		\$
9000-0002 Replace Fender System LS 1 \$853,153.72 \$853,154 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9075-0002 Disposal of Bridge Waste SF 62230 \$3.00 \$186,690	9000-0001	Bridge Lighting	EA	40	\$500.00	\$
9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9075-0002 Disposal of Bridge Waste SF 62230 \$3.00 \$186,690	9000-0002	Replace Fender System	LS	1	\$853,153.72	\$
9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9075-0002 Disposal of Bridge Waste SF 62230 \$3.00 \$186,690 9075-0002 While the Mass of the Containment SF 62230 \$3.00 \$186,690	9000-0004	Remove and Reinstall Existing Truss	LS	1		\$
9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0007 Contech Truss LS 1 \$803,700.00 \$803,700 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$
9000-0010 Miscellaneous Steel Repairs LS 1 \$005,700.00 \$005,700.00 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0006		LS	1	\$40,000.00	\$
9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0007	Contech Truss	LS	1	\$803,700.00	\$ 803,700
9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$100,000.00 \$100,000 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0010		LS	1	\$300,000.00	\$
9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$100,000.00	\$
9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9071-0151		SF	62230	\$9.00	\$
9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9073-0002	Disposal of Bridge Waste	SF	62230	\$0.30	\$ 18,669
0000 0000 141 1 141 10 0	9075-0002	Containment	SF	62230	\$3.00	\$
	9077-0002	Worker Health and Safety	SF	62230	\$0.50	\$

Sub-Total \$ 4,001,526

Total with 15% Contingency \$ 4,601,755

 $\label{lem:hard-clents} H:\PA-CLIENTS\3061\3061-Calcs\Structures\Preliminary Estimate\Preliminary Concepts Cost Estimate Worksheet: Truss-1$



Project: Grays Ferry Ave Ped Bridge

Subject: Truss Concept-2 Preliminary Cost Estimate

Designed by: NER

Date: May 19, 2010

Index No:

Job No: 3061

Checked by: Date:

9/29/11

TRUSS CONCEPT - 2 COST ESTIMATE

New Single-Span Prefabricated Truss passing over existing rehabilitated truss

<u>Item No.</u>	<u>Item</u>	<u>Unit</u>	Quantity	Unit Price	Cost
0204-0100	Class 3 Excavation	CY	121	\$45.00	\$ 5,445
0205-0100	Foreign Borrow Excavation	CY	7920	\$15.00	\$ 118,800
1001-0001	Class A Concrete (Piers and Abutments)	CY	163	\$650.00	\$ 105,950
1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$ 139,700
1002-0053	Reinforcement Bars, Epoxy Coated (Deck)	LBS	25400	\$1.71	\$ 43 ,434
1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	30070	\$1.71	\$ 51,420
1003-0008	Dowel Holes, 16" Depth	EA	66	\$30.00	\$ 1,980
1005-1143	HP 12x53 Steel Piles	LF	400	\$91.20	\$ 36,480
1018-0050	Removal of Existing Bridge	LS	1	\$50,000.00	\$ 50 ,000
9000-0001	Bridge Lighting	EA	40	\$500.00	\$ 20,000
9000-0002	Replace Fender System	LS	1	\$853,153.72	\$ 853,154
9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$ 227,500
9000-0006	Underwater Rehabilitation of Substructure (Pressure Injection Grouting)	LS	1	\$40,000.00	\$ 40,000
9000-0007	Contech Truss	LS	1	\$1,008,900.00	\$ 1,008,900
9000-0010	Miscellaneous Steel Repairs	LS	1	\$300,000.00	\$ 300,000
9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$40,000.00	\$ 40,000
9071-0151	Painting Existing Structural Steel Using Organic Zinc Coating Systems	SF	62230	\$11.50	\$ 715,645
9073-0002	Disposal of Bridge Waste	SF	62230	\$0.30	\$ 18, 669
9075-0002	Containment	SF	62230	\$3.50	\$ 217,805
9077-0002	Worker Health and Safety	SF	62230	\$0.50	\$ 31,115

Sub-Total \$ 4,025,996

Total with 15% Contingency \$ 4,629,896

H:\PA-CLIENTS\3061\3061-Calcs\Structures\Preliminary Estimate\Preliminary Concepts Cost Estimate Worksheet: Truss-2



Project: Grays Ferry Ave Ped Bridge

Subject: Truss Concept-3 Preliminary Cost Estimate

Designed by: **NER**

Date: May 19, 2010

Index No:

Job No: 3061

Date:

Checked by:

9/29/11

TRUSS CONCEPT - 3 COST ESTIMATE

Reuse existing truss with new prefabricated truss back spans

<u>Item No.</u>	<u>Item</u>	<u>Unit</u>	Quantity	Unit Price	Cost
0204-0100	Class 3 Excavation	CY	121	\$45.00	\$ 5,4 45
0205-0100	Foreign Borrow Excavation	CY	1628	\$15.00	\$ 24,420
1001-0001	Class A Concrete (Piers and Abutments)	CY	187	\$650.00	\$ 121,550
1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$ 139,700
1002-0053	Reinforcement Bars, Epoxy Coated (Deck)	LBS	25400	\$1.71	\$ 43 ,434
1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	34870	\$1.71	\$ 59,628
1003-0008	Dowel Holes, 16" Depth	EA	132	\$30.00	\$ 3,960
1005-1143	HP 12x53 Steel Piles	LF	400	\$91.20	\$ 36,480
1018-0050	Removal of Existing Bridge	LS	1	\$50,000.00	\$ 50,000
9000-0001	Bridge Lighting	EA	40	\$500.00	\$ 20,000
9000-0002	Replace Fender System	LS	1	\$467,310.00	\$ 467,310
9000-0004	Remove and Reinstall Existing Truss	LS	1	\$236,000.00	\$ 236,000
9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$ 227,500
9000-0006	Underwater Rehabilitation of Substructure (Pressure Injection Grouting)	LS	1	\$40,000.00	\$ 40,000
9000-0007	Contech Truss	LS	1	\$399,000.00	\$ 399,000
9000-0010	Miscellaneous Steel Repairs	LS	1	\$300,000.00	\$ 300,000
9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$100,000.00	\$ 100,000
9071-0151	Painting Existing Structural Steel Using Organic Zinc Coating Systems	SF	60280	\$9.00	\$ 542,520
9073-0002	Disposal of Bridge Waste	SF	60280	\$0.30	\$ 18,084
9075-0002	Containment	SF	60280	\$3.00	\$ 180 ,840
9077-0002	Worker Health and Safety	SF	60280	\$0.50	\$ 30,140

Sub-Total \$ 3,040,566

Total with 15% Contingency \$ 3,496,651



Project: Grays Ferry Ave Ped Bridge

Subject: Cable-Stay Concept-1 Preliminary Cost Estimate

Designed by: **NER**

Date: May 19, 2010

Index No:

Job No: 3061

Date:

Checked by:

AL 9/29/11

CABLE-STAY CONCEPT - 1 COST ESTIMATE

Reuse existing truss with cable-stay back spans

CY 121 \$45.00 \$ 5,445	Item No.	<u>Item</u>	<u>Unit</u>	Quantity	<u>Unit Price</u>		Cost
0205-0100 Foreign Borrow Excavation CY 1628 \$15.00 \$ 24,420 1001-0001 Class A Concrete (Piers and Abutments) CY 222 \$650.00 \$ 144,300 1001-0000 Class AAA Concrete (Deck) CY 127 \$1,100.00 \$ 139,700 1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 44,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 37937 \$1.71 \$ 64,872 1003-0008 Dowel Holes, 16" Depth EA 306 \$30.00 \$ 9,180 1005-0143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.0 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500	0204-0100	Class 3 Excavation	CY	121	\$45.00	\$	5,445
1001-0001 Class A Concrete (Piers and Abutments)	0205-0100	Foreign Borrow Excavation	CY	1628	\$15.00	\$	
1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 37937 \$1.71 \$ 64,872 1003-0008 Dowel Holes, 16" Depth EA 306 \$30.00 \$ 9,180 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LF 1080 \$130.00 \$ 40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$ 40,000 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$ 40,000 9050-0002 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$ 731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690 9075-0002 Containm	1001-0001		CY	222	\$650.00	\$	
1002-0053 Reinforcement Bars, Epoxy Coated (Deck) LBS 25400 \$1.71 \$ 43,434 1002-0053 Reinforcement Bars, Epoxy Coated (Substructure) LBS 37937 \$1.71 \$ 64,872 1003-0008 Dowel Holes, 16" Depth EA 306 \$33,000 \$ 9,180 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 227,500 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LF 1080 \$130.00 \$ 40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$ 40,000 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$ 40,000 9050-0002 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$ 731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690 9075-0002 Contain	1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$	139,700
1003-0008 Dowel Holes, 16" Depth EA 306 \$30.00 \$9,180 1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$27,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$140,000.00 \$140,000	1002-0053		LBS	25400	\$1.71	\$	
The color of the	1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	37937	\$1.71	\$	64,872
1005-1143 HP 12x53 Steel Piles LF 400 \$91.20 \$ 36,480 1018-0050 Removal of Existing Bridge LS 1 \$50,000.00 \$ 50,000 9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$ 40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$ 140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LBS 18640 \$5.70<	1003-0008	Dowel Holes, 16" Depth	EA	306	\$30.00	\$	9,180
9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$ 40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$ 140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$ 140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating System	1005-1143		LF	400	\$91.20	\$	
9000-0001 Bridge Lighting EA 40 \$500.00 \$ 20,000 9000-0002 Replace Fender System LS 1 \$467,310.00 \$ 467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$ 236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$ 227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$ 40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$ 140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$ 140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9071-0151 Painting Existing Structural Steel, Pylons LBS	1018-0050	Removal of Existing Bridge	LS	1	\$50,000.00	\$	50 ,000
9000-0002 Replace Fender System LS 1 \$467,310.00 \$467,310 9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Was	9000-0001	Bridge Lighting	EA	40		\$	20,000
9000-0004 Remove and Reinstall Existing Truss LS 1 \$236,000.00 \$236,000 9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$3.00 \$186,690 9075-0002 Containment	9000-0002	Replace Fender System	LS	1	\$467,310.00	\$	
9000-0005 Rehabilitation of Existing Stone Masonry Substructure LF 4550 \$50.00 \$227,500 9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0004	Remove and Reinstall Existing Truss	LS	1	\$236,000.00	\$	
9000-0006 Underwater Rehabilitation of Substructure (Pressure Injection Grouting) LS 1 \$40,000.00 \$40,000 9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$	
9000-0008 Bridge Railing LF 1080 \$130.00 \$140,400 9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690	9000-0006		LS	1	\$40,000.00	\$	
9000-0009 Multistrand Stay-Cable System (4-Strands) 2827 \$35.63 \$ 100,712 9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$ 300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$ 140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$ 731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9000-0008		1.12	1000	#4.20.00	φ.	140 400
9000-0010 Miscellaneous Steel Repairs LS 1 \$300,000.00 \$300,000 9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690			LF_				
9018-0001 Removal of Portion of Existing Bridge - Substructure LS 1 \$140,000.00 \$140,000 9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$18,669 9075-0002 Containment SF 62230 \$3.00 \$186,690			1.0				
9050-0001 Fabricated Structural Steel, Floor System LBS 49640 \$5.70 \$ 282,948 9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$ 731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690						_	
9050-0002 Fabricated Structural Steel, Pylons LBS 128380 \$5.70 \$ 731,766 9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690							
9071-0151 Painting Existing Structural Steel Using Organic Zinc Coating Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690							
9071-0151 Systems SF 62230 \$9.00 \$ 560,070 9073-0002 Disposal of Bridge Waste SF 62230 \$0.30 \$ 18,669 9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9030-0002		TR2	128380	\$5.70	\$	731,766
9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9071-0151		SF	62230	\$9.00	\$	560,070
9075-0002 Containment SF 62230 \$3.00 \$ 186,690	9073-0002	Disposal of Bridge Waste	SF	62230	\$0.30	\$	18,669
	9075-0002	Containment	SF	62230	\$3.00	\$	
	9077-0002	Worker Health and Safety	SF	62230	\$0.50	\$	31,115

Sub-Total \$ 4,001,011

Total with 20% Contingency \$ 4,801,213

H:\PA-CLIENTS\3061\3061-Calcs\Structures\Preliminary Estimate\Preliminary Concepts Cost Estimate Worksheet: Cable Stay-1

Project: Grays Ferry Ave Ped Bridge Index No:

Subject: Cable-Stay Concept-1 (Contech)

Job No: **3061** Checked by:

Date:

Designed by: NER
Date: May 19, 2010

9/29/11

CABLE-STAY CONCEPT - 1 (CONTECH) COST ESTIMATE

Reuse existing truss with cable-stay back spans

Item No.	<u>Item</u>	<u>Unit</u>	Quantity	<u>Unit Price</u>	Cost
0204-0100	Class 3 Excavation	CY	121	\$45.00	\$ 5, 445
0205-0100	Foreign Borrow Excavation	CY	1628	\$15.00	\$ 24,420
1001-0001	Class A Concrete (Piers and Abutments)	CY	222	\$650.00	\$ 144,300
1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$ 139,700
1002-0053	Reinforcement Bars, Epoxy Coated (Deck)	LBS	25400	\$1.50	\$ 38,100
1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	37937	\$1.50	\$ 56,906
1003-0008	Dowel Holes, 16" Depth	EA	306	\$30.00	\$ 9,180
1005-1143	HP 12x53 Steel Piles	LF	400	\$80.00	\$ 32,000
1018-0050	Removal of Existing Bridge	LS	1	\$50,000. 00	\$ 50,000
9000-0001	Bridge Lighting	EA	40	\$500.00	\$ 20,000
9000-0002	Replace Fender System	LS	1	\$467,310.00	\$ 467,310
9000-0004	Remove and Reinstall Existing Truss	LS	1	\$236,000.00	\$ 236,000
9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$ 227,500
9000-0008	Bridge Railing	LF	1080	\$130.00	\$ 140,400
9000-0006	Underwater Rehabilitation of Substructure (Pressure Injection Grouting)	LS	1	\$40,000.00	\$ 40,000
9000-0009	Contech Cable Stayed Bridge	LS	1	\$889,200.00	\$ 889,200
9000-0010	Miscellaneous Steel Repairs	LS	1	\$300,000.00	\$ 300 ,000
9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$140,000.00	\$ 140,000
9071-0151	Painting Existing Structural Steel Using Organic Zinc Coating Systems	SF	60280	\$9.00	\$ 542,520
9073-0002	Disposal of Bridge Waste	SF	60280	\$0.30	\$ 18,084
9075-0002	Containment	SF	60280	\$3.00	\$ 180,840
9077-0002	Worker Health and Safety	SF	60280	\$0.50	\$ 30,140

Sub-Total \$ 3,726,600

Total with 20% Contingency \$ 4,471,919



Project: Grays Ferry Ave Ped Bridge

Subject: Cable-Stay Concept-2 Preliminary Cost Estimate

Designed by: NER

Date: May 19, 2010

Index No:

Job No: 3061

Checked by:

Date: 9/2

CABLE-STAY CONCEPT - 2 COST ESTIMATE

Continuous spiral cable-stay spanning over existing truss

<u>Item No.</u>	<u>Item</u>	<u>Unit</u>	Ouantity	<u>Unit Price</u>		<u>Cost</u>
0205-0100	Foreign Borrow Excavation	CY	7920	\$15.00	- \$	118,800
1001-0001	Class A Concrete (Piers and Abutments)	CY	140	\$650.00	\$	91,000
1001-0000	Class AAA Concrete (Deck)	CY	127	\$1,100.00	\$	139,700
1002-0053	Reinforcement Bars, Epoxy Coated (Deck)	LBS	25400	\$1.71	\$	43 ,434
1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	12522	\$1.71	\$	21,413
1003-0008	Dowel Holes, 16" Depth	EA	398	\$30.00	\$	11,940
1005-1143	HP 12x53 Steel Piles	LF	400	\$91.20	\$	36,480
1018-0050	Removal of Existing Bridge	LS	1	\$50,000.00	\$	50,000
9000-0001	Bridge Lighting	EA	40	\$500.00	\$	20,000
9000-0002	Replace Fender System	LS	1	\$853,153.72	\$	853,154
9000-0004	Remove and Reinstall Existing Truss	LS	1	\$236,000.00	\$	236,000
9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$	227,500
9000-0006	Underwater Rehabilitation of Substructure (Pressure Injection Grouting)	LS	1	\$40,000.00	\$	40,000
9000-0008	Bridge Railing	LF	1080	\$130.00	\$	140,400
9000-0009	Multistrand Stay-Cable System (4-Strands)		7772	\$35.63	\$	276,878
9000-0010	Miscellaneous Steel Repairs	LS	1	\$300,000.00	\$	300,000
9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$140,000.00	\$	140,000
9050-0001	Fabricated Structural Steel, Pylons	LBS	231668	\$5.70	\$	1,320,508
9050-0002	Fabricated Structural Steel, Floor System	LBS	82110	\$5.70	\$	468,027
9071-0151	Painting Existing Structural Steel Using Organic Zinc Coating Systems	SF	62230	\$9.00	\$	560,070
9073-0002	Disposal of Bridge Waste	SF	62230	\$0.30	\$	18,669
9075-0002	Containment	SF	62230	\$3.00	\$	186,690
9077-0002	Worker Health and Safety	SF	62230	\$0.50	\$	31,115

Sub-Total \$ 5,331,776

Total with 20% Contingency \$ 6,398,132

H:\PA-CLIENTS\3061\3061-Calcs\Structures\Preliminary Estimate\Preliminary Concepts Cost Estimate Worksheet: Cable Stay-2

Project: Grays Ferry Ave Ped Bridge

Index No: Subject: Cable-Stay Concept-3 Preliminary Cost Estimate

Designed by: **NER**

Job No: **3061** Checked by:

Date: May 19, 2010

AL 9/29/11 Date:

CABLE-STAY CONCEPT - 3 COST ESTIMATE

Two tower cable stayed structure

Item No.	<u>Item</u>	<u>Unit</u>	Ouantity	Unit Price	Cost
0204-0100	Class 3 Excavation	CY	121	\$45.00	\$ 5 ,445
0205-0100	Foreign Borrow Excavation	CY	1628	\$15.00	\$ 24,420
1001-0001	Class A Concrete (Piers and Abutments)	CY	163	\$650.0 0	\$ 105,950
1001-0000	Class AAA Concrete (Deck)	CY	97	\$1,100.00	\$ 106,700
	Reinforcement Bars, Epoxy Coated (Deck)	LBS	19400	\$1.71	\$ 33,174
1002-0053	Reinforcement Bars, Epoxy Coated (Substructure)	LBS	26621	\$1.71	\$ 45,522
1003-0008	Dowel Holes, 16" Depth	EA	196	\$30.00	\$ 5,880
	HP 12x53 Steel Piles	LF	400	\$91.20	\$ 36,480
1018-0050	Removal of Existing Bridge	LS	1	\$50,00 0.00	\$ 50,000
9000-0001	Bridge Lighting	EA	40	\$500.00	\$ 20,000
9000-0002	Replace Fender System	LS	1	\$853,153.72	\$ 853,154
9000-0005	Rehabilitation of Existing Stone Masonry Substructure	LF	4550	\$50.00	\$ 227,500
	Underwater Rehabilitation of Substructure (Pressure Injection Grouting)	LS	1	\$40,000.00	\$ 40,000
9000-0007	Contech Truss (Approach Spans)	LS	1	\$171,000.00	\$ 171,000
	Bridge Railing	LF	1080	\$130.00	\$ 140,400
9000-0009	Multistrand Stay-Cable System (4-Strands)		2928	\$35.63	\$ 104,310
9000-0010	Miscellaneous Steel Repairs	LS	1	\$300,000.00	\$ 300, 000
9018-0001	Removal of Portion of Existing Bridge - Substructure	LS	1	\$80,000.00	\$ 80,000
9050-0001	Fabricated Structural Steel, Floor System	LBS	63618	\$5.70	\$ 362,623
9050-0002	Fabricated Structural Steel, Pylons	LBS	153746	\$5.70	\$ 876,352
907/1-0151	Painting Existing Structural Steel Using Organic Zinc Coating Systems	SF	62230	\$9.00	\$ 560,070
9073-0002	Disposal of Bridge Waste	SF	62230	\$0.30	\$ 18,669
9075-0002	Containment	SF	62230	\$3.00	\$ 186,690
9077-0002	Worker Health and Safety	SF	62230	\$0.50	\$ 31,115

Sub-Total \$ 4,385,453

Total with 20% Contingency \$ 5,262,544

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Approximate Weight

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

AL 06/01/10

The following calculates the approximate weight of the existing truss in order to check the feasability of crane picking from a barge.

END BOTTOM CHORD (L0 - L1)

2 - C15 x 35 with Single Lacing (top and bottom)

Channel weight (2 channels)	w =	70	plf
Length (L0-L1)	L =	27.75	ft
Lattice bar length	LI =	1.41	ft
Lattice bar width	wl =	2.50	in
Lattice bar thickness	tl =	0.38	in
Length of lattice bar along bottom chord	L2 =	9.25	in
Weight of lattice per linear foot of bottom chord	W2 =	11.64	plf
Total weight of steel per linear foot of bottom chord		81.64	plf
Number of bottom chords	Nc =	4.	
Total weight of L0-L1 Bottom Chord		9062	lbs

BOTTOM CHORD (L1 - L3)

2 - C15 x 50 with Single Lacing

Channel weight (2 channels)	w = [10.0 plf
Length (L1-L3)	L =	55.5 ft
Lattice bar length	L1 =	1.28 ft
Lattice bar width	wl =	2.50 in
Lattice bar thickness	tl =	0.38 in
Length of lattice bar along bottom chord	L2 =	8 in
Weight of lattice per linear foot of bottom chord	W2 =	12.21 plf
Total weight of steel per linear foot of bottom chord		112.21 plf
Number of bottom chords	Nc =	4
Total weight of L1-L3 Bottom Chord		24911 lbs

BOTTOM CHORD (L3 - L4)

2 - C15 x 50 with Single Lacing

Channel weight (2 channels)	w =	100	pif
Length (L3-L4)	L=	27.75	ft
Lattice bar length	LI =	1.28	ft
Lattice bar width	wl =	2.50	in
Lattice bar thickness	tl =	0.38	in
Length of lattice bar along bottom chord	L2 =	8	in
Weight of lattice per linear foot of bottom chord	W2 =[12.21	plf
Total weight of steel per linear foot of bottom chord		112.21	plf
Number of bottom chords	Nc =	4	
Total weight of L3-L4 Bottom Chord		12456	lbs

TOP CHORD (U1 - U3)

2 - C15 x 40 with Double Lacing

Channel weight (2 channels)	w =	80	plf
Length (U1-U3)	L =	55.5	ft
Lattice bar length	LI =	2.50	ft
Lattice bar width	wl =	2.50	in
Lattice bar thickness	ti =	0.44	in
Length of lattice bar along top chord	L2 =	18	in
Weight of lattice per linear foot of top chord	W2 =	24.81	plf
Total weight of steel per linear foot of top chord		104.81	plf
Number of top chords	Nc =	4	
Total weight of U1-U3 Top Chord		23268	lbs

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Approximate Weight

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

AL 06/01/10 Date:

TOP CHORD (U3 - U4)

2 - C15 x 50 with Double Lacing

Channel weight (2 channels)	w = [100 plf
Length (L3-U4)	L =	27.75 ft
Lattice bar length	Lt = 📗	2.50 ft
Lattice bar width	wi =	2.50 in
Lattice bar thickness	tl = 📗	0.50 in
Length of lattice bar along bottom chord	L2 =	18 in
Weight of lattice per linear foot of top chord	W2 =	28.36 plf
Total weight of steel per linear foot of top chord		128.36 plf
Number of top chords	Nc =	4
Total weight of U3-U4 Top Chord		14248 lbs

FLOORBEAM (F1 & F2)

Web depth	d =	50	lin
Web Thickness	t =	0.5625	in
Weight of one flange angle (L6x6x9/16)	wa =	22	plf
Cover plate thickness	tc =	0.5	in
Cover plate width	wc =	14	in
Floorbeam Length	L =	15.77	ft
Weight of one floorbeam		3648	lbs
Number of F1 & F2 floorbeams	Nf =	6	
Total weight of F1 & F2 floorbeams		21 891	lbs

FLOORBEAM (EF)

Web depth	d =	46	in
Web Thickness	t =	0.5625	in
Weight of one flange angle (L6x6x5/8)	wa =	24.3	plf
Floorbeam Length	L =	15.77	ft
Weight of one floorbeam		2921	lbs
Number of EF floorbeams	Nf =	2	
Total weight of EF floorbeams		5843	lbs

STRINGERS (S & S7)

Web depth	d =	39	in
Web Thickness	t =	0.50	in
Weight of one flange angle (L6x4x5/8)	wa =	20	plf
Stringer Length	L =	27.75	ft
Weight of one stringer		4061	lbs
Number of S & S7 stringers	Ns =	8	
Total weight of S & S7 stringers		32491	lbs

END STRINGERS (S1 & S2)

Web depth	d =	39 in
Web Thickness	t = 🛮	0.50 in
Weight of one flange angle (L6x4x5/8)	wa =	20 plf
Stringer Length	L = [27.75 ft
Weight of one stringer		4061 lbs
Number of S1 & S2 stringers	Ns =	4
Total weight of S1 & S2 stringers		16245 lbs

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Approximate Weight

Designed by: NER

Date: May 6, 2010

Index No:

Job No: **3061**

Checked by:

Date: 06/01/10

CENTER STRINGERS (S3 - S6)

Web depth	d =	39	in
Web Thickness	t =	0.50	in
Weight of one flange angle (L6x4x5/8)	wa =	19.8	plf
Cover plate thickness	tc =	0.5625	in
Cover plate width	wc =	14	in
Stringer Length	L =	27.75	ft
Weight of one stringer		5526	lbs
Number of stringers	Ns =	4	
Total weight of S3 - S6 stringers		22105	lbs

STRINGER LATERALS (L3.5x3x5/16)

Weight of one angle (L3.5x3x5/16)	wa = 6.65 plf
Approximate length of laterals	La = 7.83 ft
Number of laterals	Na = 40
Total weight of laterals	2084 lbs

BOTTOM TRUSS LATERALS (L1 - L6) (L5x3.5x1/2)

Weight of one angle (L5x3.5x1/2)	wa = 13.6 plf
Approximate length of laterals	La = 30.67 ft
Number of laterals	Na = 12
Total weight of laterals	5005 lbs

BOTTOM TRUSS LATERALS (L7 - L9) (L5x3.5x1/2)

Weight of one angle (L5x3.5x1/2)	wa = 13.6 plf
Approximate length of laterals	La = 20.25 ft
Number of laterals	Na = 4
Total weight of laterals	1102 lbs

BOTTOM TRUSS LATERALS (L10) (L5x3.5x1/2)

Weight of one angle (L5x3.5x1/2)	wa = 13.6 plf	
Approximate length of laterals	La = 13.50 ft	
Number of laterals	Na = 4	
Total surface area of laterals	734 lbs	i

END POSTS (L0-U1)

2 - C15 x 35 with Double Lacing one side & Cover Plate other side

Channel weight (2 channels)	w =	70 plf
Length (L0-U1)	L=	39.42 ft
Lattice bar length	LI =	2.54 ft
Lattice bar width	wl =	2.50 in
Lattice bar thickness	tl =	0.44 in
Length of lattice bar along post	L2 =	19 in
Width of cover plate	wc =	22 in
Thickness of cover plate	tc =	0.5 in
Weight of lattice and cover plate per linear foot of post	A2 =	61.33 plf
Total weight of steel per linear foot of post	1	131.33 plf
Number of bottom end posts	Nc =	4
Total weight of L0-U1 end posts	1	20706 lbs

INTERMEDIATE END POSTS (L4-U3)

2 - Built-up channels (4-L3.5x3.5x5/8 & 18x5/8" web PL) with Double Lacing

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Approximate Weight Job No: 3061 Designed by: NER Checked by: 06/01/10 Date: May 6, 2010 Date: Channel web depth 18 in dc = Channel web thickness tc = 0.625 in Weight of built-up channels 124.56 plf Length (L4-U3) L = 42.00 ft Lattice bar length LI = 2.67 ft Lattice bar width wl =2.50 in Lattice bar thickness tl = 0.44 in Length of lattice bar along post L2 = 20 in Weight of lattice per linear foot of post A2 =23.82 plf Total weight of steel per linear foot of post 148.38 plf Number of intermediate end posts Nc = Weight of tie plate 1 78.26 lbs Weight of tie plate 2 58.70 lbs Number of tie plates Nt =16 Total weight of L0-U1 end posts 27120 lbs INTERMEDIATE POSTS (U1-L1, U2-L2, U3-L3) 2 - C15x33 channels with Double Lacing Channel weight (2 channels) 66 plf w = Average Length of posts L= 29.10 ft Lattice bar length 1.23 ft LI = 2.50 in Lattice bar width wl =Lattice bar thickness tl =0.38 in Length of lattice bar along post L2 =6 in Weight of lattice per linear foot of post 31.37 plf W2 =Total weight of steel per linear foot of post 97.37 plf Number of intermediate posts Nc = 12 Total weight of L0-U1 end posts 34006 lbs **CENTER POSTS (L4-U4)** 2 - C12x25 channels with Double Lacing Channel weight (2 channels) 50 plf w = 29.98 ft Length of posts L= Lattice bar length 2.06 ft LI = Lattice bar width wl =2.25 in Lattice bar thickness tl = 0.38 in Length of lattice bar along post L2 = 15 in Weight of lattice per linear foot of post 18.95 plf W2 =Total weight of steel per linear foot of post 68.95 plf Number of center posts Nc = Total weight of L4-U4 center posts 4134 lbs SUB POSTS (LM-UM) 2 - C12x25 channels with Double Lacing Channel weight (2 channels) 50 plf w =Length of posts L= 29.94 ft Lattice bar length LI = 1.28 ft Lattice bar width wl = 2.25 in

Lattice bar thickness

Number of SUB posts

Length of lattice bar along post

Total weight of LM-UM sub posts

Weight of lattice per linear foot of post

Total weight of steel per linear foot of post

0.38 in

7.5 in

23.54 plf

73.54 plf

8807 lbs

tI =

L2 =

W2 =

Nc =

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Approximate Weight

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

Date: 06/01/10

DIAGONALS (L1-U2)

2 - C15x33 channels with Double Lacing

Channel weight (2 channels)	w =	66 pif	
Length of posts	L =	37.63 ft	
Lattice bar length	LI =	2.52 ft	
Lattice bar width	wi =	2.50 in	
Lattice bar thickness	tl =	0.44 in	
Length of lattice bar along diagonal	L2 =	18.75 in	
Weight of lattice per linear foot of diagonal	W2 =	24.02 plf	:
Total weight of steel per linear foot of diagonal		90.02 plf	
Number of L1-U2 diagonals	Nc =	4	
Total weight of L1-U2 diagonals		13548 lbs	5

DIAGONALS (L2-U3)

2 - C15x40 channels with Double Lacing

Channel weight (2 channels)	w =	80 p	olf
Length of posts	L=	39.06 f	t
Lattice bar length	ப =	2.52 f	t
Lattice bar width	wl =	2.50 ji	n
Lattice bar thickness	ti = 📗	0.44 ii	n
Length of lattice bar along diagonal	L2 =	18.75 ii	n
Weight of lattice per linear foot of diagonal	W2 =	24.02 p	olf
Total weight of steel per linear foot of diagonal	Ī	104.02 p	olf
Number of L2-U3 diagonals	Nc =	4	
Total weight of L2-U3 diagonals		16253 II	bs

SUB-STRUTS (L3-MC)

2 - C12x25 channels with Double Lacing

Channel weight (2 channels)	w =	50	plf
Length of posts	L =	18.68	ft
Lattice bar length	LI =	1.28	ft
Lattice bar width	wl =	2.25	in
Lattice bar thickness	tl =	0.38	in
Length of lattice bar along strut	L2 =	7.25	in
Weight of lattice per linear foot of strut	W2 =[24.35	plf
Total weight of steel per linear foot of strut	[74.35	plf
Number of L3-MC struts	Nc =	4	
Total weight of L3-MC struts	[5555	lbs

GIRDERS (G1 & G2)

Web depth	d = 30 in
Web thickness	t = 0.375 in
Weight of one flange angle (L3.5x3x5/16)	wa = 6.65 plf
Girder Length	L = 15.88 ft
Weight of one girder	1030 lbs
Number of girders	Ng = 3
Total weight of G1 & G2 girders	3090 lbs

END PORTALS (P10)

Top Angle (2 - L5x3.5x7/16; LLH)	
Top Angle weight	w1 = 11.9 plf
Top angle length	L1 = 18.83 ft
Total weight of top angle	W1 = 448.23 lbs

Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Approximate Weight Job No: 3061 Designed by: NER Checked by: 06/01/10 Date: May 6, 2010 Date: Bottom Angle (2 - L5x3.5x7/16; LLH) Bottom Angle weight w2 =11.9 plf Bottom angle length L2 =15.06 ft Total weight of bottom angle 358.49 lbs W2 = Interior Angles (L3.5x3.5x3/8) Interior Angle weight w3 = 9.74 plf Total interior angle length L3 =63.83 ft Total weight of interior angles W3 =621.74 lbs Number of P10 portals Np =2 Total weight of P10 portals 2856.92 lbs **SWAY FRAMES (F)** Top Angle (2 - L5x3.5x7/16; LLH) Top Angle weight w1 =11.9 plf Top angle length L1 =18.83 ft Total weight of top angle W1 =448.23 lbs Bottom Angle (2 - L5x3.5x7/16; LLH) Bottom Angle weight w2 =11.9 plf Bottom angle length L2 = 15.25 ft Total weight of bottom angle W2 =362.95 lbs Interior Angles (L3.5x3.5x3/8) Interior Angle weight w3 =9.74 plf Total interior angle length L3 =68.50 ft Total weight of interior angles 667.19 lbs W3 =Number of F sway frames Np = Total weight of F sway frames 2956.75 lbs **CENTER PORTALS** Top Angle (2 - L5x3.5x7/16; LLH) Top Angle weight w1 =11.9 plf Top angle length L1 =18.83 ft Total weight of top angle W1 =448.23 lbs Bottom Angle (2 - L5x3.5x7/16; LLH) Bottom Angle weight w2 = 11.9 plf Bottom angle length L2 = 15.57 ft Total weight of bottom angle W2 = 370.64 lbs Interior Angles (L3.5x3.5x3/8) & k-brace (2 - L3.5x3.5x3/8) Interior Angle weight w3 = 9.74 plf Total interior angle length L3 =130.50 ft Total weight of interior angles W3 = 1271.07 lbs Number of center portals Np = Total weight of center portals 4179.88 lbs **TOP LATERALS (T1-T3)** 4 - L3x3.5x5/16 (LLH) with Double Lacing Weight of one angle wa = 6.65 plf Lattice bar length LI = 1.57 ft Lattice bar width wl =2.25 in

AMMANN

&

WHITNEY

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Approximate Weight Job No: 3061 AL 06/01/10 Designed by: NER Checked by: Date: May 6, 2010 Date: Lattice bar thickness tl = 0.38 in Length of lattice bar along lateral L2 = 11.5 in Weight of lattice per linear foot of lateral W2 =18.85 plf Total weight of steel per linear foot of lateral 45.45 plf Number of laterals Nc = Approximate length of top laterals 29.5 ft Total surface area of T1-T3 top laterals 10726.05 lbs **STAIR FRAME (SF1)** 2-C3x13.75 frames with C7x12.25 treads Weight of one C8x13.75 wc1 = 13.75 plf Length of C8x13.75 Lf =38.86 ft Weight of one of C7x12.25 wc2 = 12.25 plf Length of one tread Lt = 1.99 ft Number of treads Nt = 12 Total weight of SF1 frame and treads 1361.24 lbs **STAIR FRAME (SF2)** 2-C3x13.75 frames with C7x12.25 treads Weight of one C8x13.75 wc1 = 13.75 plf Length of C8x13.75 55.21 ft Lf = Weight of one C7x12.25 12.25 plf wc2 = Length of one tread Lt = 1.99 ft Number of treads Nt =24 Total weight of SF1 frame and treads 2103.17 lbs SUB TOTAL OF WEIGHT OF STEEL 348847 LBS

ADD 15% FOR GUSSETS, PLATES, RIVETS, MISC. BRACKETS, STIFFENERS, ETC.

TOTAL WEIGHT OF STEEL TO LIFT ABOVE BOTTOM CHORD

401180 LBS

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Approximate Weight

JOD NO.

Index No:

Job No: **3061**

Designed by: NER

NER

Checked by: Date: AL 06/01/10

ADDITIONAL WEIGHT OF TRUSS BELOW BOTTOM CHORD

The following is the calculation of the additional weight of the steel members below the bottom chord since the truss may be lifted with or without these additional members.

WHEEL GIRDER (WG1)

Date: May 6, 2010

Web depth of constant web depth portion	dc =	60.5 in
Length of constant web depth portion	Lc =	6.5 ft
Average web depth of variable web depth portion	dv =	35.875 in
Length of variable depth portion	Lv =	11.625 ft
Web thickness	t =	0.375 in
Weight of one top flange angle (L6x4x3/8)	wta =	12.20 plf
Total girder length	L=	18.13 ft
Weight on one bottom flange angle (L4x4x3/8)	wba =	9.72 plf
Length of bottom flange angle		22.00 ft
Total weight of WG1 girder		1903.90 lbs

WHEEL GIRDER (WG2)

d =	18	in
t =	0.375	in
wta =	12.7	plf
wba =	16	plf
L =	12.13	ft
	974.47	lbs
Ng =	4	
	3897.88	lbs
	t = wta = wba = L =	t = 0.375 wta = 12.7 wba = 16 L = 12.13 974.47

PINION GIRDER (PG)

Web depth of constant web depth portion	dc =	68.5 in	ı
Length of constant web depth portion	Lc =	6.5 ft	1
Average web depth of variable web depth portion	dv =	40 in	1
Length of variable depth portion	Lv =	11.625 ft	:
Web thickness	t =	0.375 in	1
Weight of one top flange angle (L6x4x3/8)	wta =	12.20 pl	lf
Total girder length	L =	18.13 ft	
Weight on one bottom flange angle (L4x4x3/8)	wba =	9.72 pl	lf
Length of bottom flange angle	Į.	23.00 ft	
Total weight of WG1 girder		2050.89 lb	ວຣ

CENTER GIRDERS (CG1 & CG2)

Web depth	d =	60 in
Web thickness	t =	0.625 in
Weight of one flange angle (L6x6x1/2)	wa =	19.6 plf
Cover plate thickness	tc =	0.5 in
Cover plate width	wc =	14 in
Average Girder Length	L =	21.79 ft
Weight of one girder		5008.20 lbs
Number of CG girders	Ng =	2
Total weight of WG2 girders		10016.40 lbs

WEDGE GIRDERS

Web depth	d = 48.5 in
Web thickness	t = 0.375 in
Weight of one flange angle (L6x4x3/8)	wa = 12.20 plf
Girder Length	L = 4.50 ft

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Approximate Weight Job No: 3061 Designed by: NER Checked by: 06/01/10 Date: May 6, 2010 Date: Weight of one girder 498.10 lbs Number of wedge girders Ng =Total weight of WG2 girders 1992.38 lbs **BOLT GIRDERS** Web depth 39.75 in d =Web thickness 0.5 in t = Weight of one flange angle (L6x4x3/8) 12.20 plf wa = Girder Length 4.50 ft L =Weight of one girder 523.94 lbs Number of wedge girders Ng = Total weight of WG2 girders 1047.87 lbs TOTAL ADDITIONAL WEIGHT OF STEEL BELOW BOTTOM CHORD 20909 LBS ADD 15% FOR MISC. MACHINERY CONNECTIONS, PLATES, ETC. 3136 LBS TOTAL LBS OF STEEL TO LIFT ABOVE & BELOW BOTTOM CHORD 425230 LBS

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

AL

Date: 5/17/10

The following calculates the approximate total square feet of steel of the existing steel truss to be painted for rehabilitation. See existing plans for member designations.

END BOTTOM CHORD (L0 - L1)

2 - C15 x 35 with Single Lacing (top and bottom)

Channel depth	d =	15	lin
Channel flange width	b =	3.42	in
Length (L0-L1)	L=	27.75	ft
Perimeter of one channel	Pc =	3.64	ft
Lattice bar length	LI =	1.41	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	0.586	sf
Length of lattice bar along bottom chord	L2 =	9.25	in
Area of lattice per linear foot of bottom chord	A2 =	1.52	sf/ft
Total surface area of steel per linear foot of bottom chord		8.80	sf/ft
Number of bottom chords	Nc =	4	
Total surface area of L0-L1 Bottom Chord	[976.83	sf

BOTTOM CHORD (L1 - L3)

2 - C15 x 50 with Single Lacing

Channel depth	d =	15	in
Channel flange width	b =	3.72	in
Length (L1-L3)	L=	55.5	ft
Perimeter of one channel	Pc =	3.74	ft
Lattice bar length	LI =	1.28	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	0.532	sf
Length of lattice bar along bottom chord	L2 =	8	in
Area of lattice per linear foot of bottom chord	A2 =	1.60	sf/ft
Total surface area of steel per linear foot of bottom chord		9.08	sf/ft
Number of bottom chords	Nc =	4	
Total surface area of L1-L3 Bottom Chord		2014.66	sf

BOTTOM CHORD (L3 - L4)

2 - C15 x 50 with Single Lacing

Channel depth	d =	15	lin
Channel flange width	b =	3.72	D195711
Length (L3-L4)	L =	27.75	ft
Perimeter of one channel	Pc =	3.74	ft
Lattice bar length	LI =	1.28	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	A1 =	0.532	sf
Length of lattice bar along bottom chord	L2 =	8	in
Area of lattice per linear foot of bottom chord	A2 =	1.60	sf/ft
Total surface area of steel per linear foot of bottom chord		9.08	sf/ft
Number of bottom chords	Nc =	4	
Total surface area of L3-L4 Bottom Chord		1007.33	sf

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Index No:

Job No: **3061**

Checked by: AL

Date: 5/17/10

TOP CHORD (U1 - U3)

2 - C15 x 40 with Double Lacing

Channel depth	d =	15	lin
Channel flange width	b =	3.52	in
Length (U1-U3)	L =	55.5	ft
Perimeter of one channel	Pc =	3.67	ft
Lattice bar length	LI =	2.50	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	1.042	sf
Length of lattice bar along bottom chord	L2 =	18	in
Area of lattice per linear foot of bottom chord	A2 =	2.78	sf/ft
Total surface area of steel per linear foot of bottom chord	Į.	10.12	sf/ft
Number of bottom chords	Nc =	4	
Total surface area of U1-U3 Top Chord		2247.63	sf

TOP CHORD (U3 - U4)

2 - C15 x 50 with Double Lacing

Channel depth	d =	15	in
Channel flange width	b =	3.72	li.
Length (L3-U4)	L =	27.75	ft
Perimeter of one channel	Pc =	3.74	ft
Lattice bar length	LI =[2.50	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	1.042	sf
Length of lattice bar along bottom chord	L2 =	18	in
Area of lattice per linear foot of bottom chord	A2 =[2.78	sf/ft
Total surface area of steel per linear foot of bottom chord	[10.26	sf/ft
Number of bottom chords	Nc =	4	
Total surface area of U3-U4 Top Chord	[1138.61	sf

FLOORBEAM (F1 & F2)

Web depth	d = 50 in
Flange width	b = 14 in
Floorbeam Length	L = 15.77 ft
Surface Area of one floorbeam	205.02 sf
Number of F1 & F2 floorbeams	Nf = 6
Total surface area of F1 & F2 floorbeams	1230.13 sf

FLOORBEAM (EF)

Web depth	d = 46 in	
Flange width	b = 12.56 in	
Floorbeam Length	L = 15.77 ft	
Surface Area of one floorbeam	186.95 sf	
Number of F1 & F2 floorbeams	Nf = 2	
Total surface area of F1 & F2 floorbeams	373.90 sf	

STRINGERS (S & S7)

Web depth	d =	39 in	
Flange width	b =	14 in	
Stringer Length	L =	27.75 ft	
Surface Area of one stringer	F	309.88 sf	
Number of S & S7 stringers	Ns =	8	
Total surface area of S & S7 stringers		2479.00 sf	F

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

Date: 5/17/10

END STRINGERS (S1 & S2)

Web depth	d = 39 in
Flange width	b = 14 in
Stringer Length	L = 27.75 ft
Surface Area of one stringer	309.88 sf
Number of S1 & S2 stringers	Ns = 4
Total surface area of S1 & S2 stringers	1239.50 sf

CENTER STRINGERS (S3 - S6)

Web depth	d =	39 in
Flange width	b =	14 in
Stringer Length	L =	27.75 ft
Surface Area of one stringer	30	09.88 sf
Number of stringers	Vs =	4
Total surface area of S3 - S6 stringers	123	39.50 sf

STRINGER LATERALS (L3.5x3x5/16)

Length of first angle leg	L1 =	3.5 in
Length of second angle leg	L2 =	3 in
Perimeter of angle	Pa =	1.083 ft
Approximate length of laterals	La =	7.83 ft
Number of laterals	Na =	40
Total surface area of laterals		339.44 sf

BOTTOM TRUSS LATERALS (L1 - L6) (L5x3.5x1/2)

Length of first angle leg	L1 = 5 in
Length of second angle leg	L2 = 3.5 in
Perimeter of angle	Pa = 2.250 ft
Approximate length of laterals	La = 30.67 ft
Number of laterals	Na = 12
Total surface area of laterals	828.09 sf

BOTTOM TRUSS LATERALS (L7 - L9) (L5x3.5x1/2)

Length of first angle leg	L1 = 5 in
Length of second angle leg	L2 = 3.5 in
Perimeter of angle	Pa = 2.250 ft
Approximate length of laterals	La = 20.25 ft
Number of laterals	Na = 4
Total surface area of laterals	182.25 sf

BOTTOM TRUSS LATERALS (L10) (L5x3.5x1/2)

Length of first angle leg	L1 =	5 in
Length of second angle leg	L2 =	3.5 in
Perimeter of angle	Pa =	2.250 ft
Approximate length of laterals	La =	13.50 ft
Number of laterals	Na =	4
Total surface area of laterals		121.50 sf

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

. NEK

Date: May 6, 2010

Index No:

Job No: **3061**

Checked by:

ed by: *水*に Date: *ろ/パ*

5/17/10

END POSTS (L0-U1)

2 - C15 x 35 with Double Lacing one side & Cover Plate other side

Channel depth	d =	15	in
Channel flange width	b =	3.42	in
Length (L0-U1)	L=	39.42	ft
Perimeter of one channel	Pc=	3.64	ft
Lattice bar length	LI =	2.54	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	Al =	1.059	sf
Length of lattice bar along post	L2 =	19	in
Area of lattice and cover plate per linear foot of post	A2 =	3.17	sf/ft
Total surface area of steel per linear foot of post		10.45	sf/ft
Number of bottom end posts	Nc =	4	
Total surface area of L0-U1 end posts		1647.78	sf

INTERMEDIATE END POSTS (L4-U3)

2 - Built-up channels with Double Lacing

Channel depth	d = 📗	18.5	lin
Channel flange width	b =	4.125	in
Length (L4-U3)	L =	42.00	ft
Perimeter of one channel	Pc=	4.46	ft
Lattice bar length	LI =	2.67	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	1.111	sf
Length of lattice bar along post	L2 =	20	in
Area of lattice per linear foot of post	A2 =	2.67	sf/ft
Total surface area of steel per linear foot of post		11.58	sf/ft
Number of intermediate end posts	Nc =	4	
Total surface area of L0-U1 end posts		1946.00	sf

INTERMEDIATE POSTS (U1-L1, U2-L2, U3-L3)

2 - C15x33 channels with Double Lacing

Channel depth	d =	15	in
Channel flange width	b =	3.4	in
Average Length of posts	L =	29.10	ft
Perimeter of one channel	Pc =	3.63	ft
Lattice bar length	LI =	1.23	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	0.512	sf
Length of lattice bar along post	L2 =	6	in
Area of lattice per linear foot of post	A2 =	4.10	sf/ft
Total surface area of steel per linear foot of post	ĺ	11.36	sf/ft
Number of intermediate posts	Nc =	12	
Total surface area of L0-U1 end posts	ſ	3968.84	sf

CENTER POSTS (L4-U4)

2 - C12x25 channels with Double Lacing

Channel depth	d =	12 in
Channel flange width	b =	3.05 in
Length of posts	L =	29.98 ft
Perimeter of one channel	Pc =	3.02 ft
Lattice bar length	니=[2.06 ft
Lattice bar width	wl =	2.25 in
Surface area of one lattice bar	AI =[0.773 sf

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Job No: **3061**

Designed by: NER

Date: May 6, 2010

Checked by:

Index No:

Date:

Length of lattice bar along post	L2 =	15	in
Area of lattice per linear foot of post	A2 =	2.48	sf/ft
Total surface area of steel per linear foot of post		8.51	sf/ft
Number of center posts	Nc =	2	
Total surface area of L4-U4 center posts		510.15	sf

SUB POSTS (LM-UM)

2 - C12x25 channels with Double Lacing

Channel depth	d =	12 in	1
Channel flange width	b =	3.05 in	1
Length of posts	L=[29.94 ft	:
Perimeter of one channel	Pc =	3.02 ft	:
Lattice bar length	LI =	1.28 ft	1
Lattice bar width	wl =	2.25 in	1
Surface area of one lattice bar	AI =	0.480 st	f
Length of lattice bar along post	L2 =	7.5 in	1
Area of lattice per linear foot of post	A2 =	3.08 st	f/ft
Total surface area of steel per linear foot of post		9.11 st	f/ft
Number of SUB posts	Nc =	4	
Total surface area of LM-UM sub posts		1090.72 st	f

DIAGONALS (L1-U2)

2 - C15x33 channels with Double Lacing

Channel depth	d =	15	in
Channel flange width	b =	3.40	in
Length of posts	L =	37.63	ft
Perimeter of one channel	Pc=	3.63	ft
Lattice bar length	LI =	2.52	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =	1.050	sf
Length of lattice bar along diagonal	L2 =	18.75	in
Area of lattice per linear foot of diagonal	A2 =	2.69	sf/ft
Total surface area of steel per linear foot of diagonal		9.96	sf/ft
Number of L1-U2 diagonals	Nc =	4	
Total surface area of L1-U2 diagonals		1498.31	sf

DIAGONALS (L2-U3)

2 - C15x40 channels with Double Lacing

			1.
Channel depth	d =	15	in
Channel flange width	b =	3.52	in
Length of posts	L =	39.06	ft
Perimeter of one channel	Pc =	3.67	ft
Lattice bar length	LI =	2.52	ft
Lattice bar width	wl =	2.50	in
Surface area of one lattice bar	AI =[1.050	sf
Length of lattice bar along diagonal	L2 =	18.75	in
Area of lattice per linear foot of diagonal	A2 =[2.69	sf/ft
Total surface area of steel per linear foot of diagonal		10.04	sf/ft
Number of L2-U3 diagonals	Nc =	4	
Total surface area of L2-U3 diagonals		1568.06	sf

SUB-STRUTS (L3-MC)

2 - C12x25 channels with Double Lacing

Channel depth	d =	12 ji

Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Rehab Quantities Job No: 3061 Designed by: NER AL Checked by: Date: May 6, 2010 5/17/10 Date: Channel flange width 3.05 in b = Length of posts 18.68 ft L= Perimeter of one channel Pc = 3.02 ft Lattice bar length LI = 1.28 ft Lattice bar width wi =2.25 in Surface area of one lattice bar AI = 0.480 sf Length of lattice bar along strut L2 = 7.25 in Area of lattice per linear foot of strut A2 =3.18 sf/ft Total surface area of steel per linear foot of strut 9.21 sf/ft Number of L3-MC struts Nc = Total surface area of L3-MC struts 688.39 sf GIRDERS (G1 & G2) Web depth d =30 in Flange width b = 7.5 in Girder Length L = 15.88 ft Surface Area of one girder 119.06 sf Number of girders Ng =Total surface area of S3 - S6 stringers 357.19 sf **END PORTALS (P10)** Top Angle (2 - L5x3.5x7/16; LLH) Top Angle perimeter P1 = Top angle length 18.83 ft L1 = Surface Area of top angle A1 =508.50 sf Bottom Angle (2 - L5x3.5x7/16; LLH) Bottom Angle perimeter P2 =27 in Bottom angle length L2 =15.06 ft Surface Area of bottom angle A2 =406.69 sf Interior Angles (L3.5x3.5x3/8) Interior Angle perimeter P3 =14 in Total interior angle length L3 =63.83 ft Surface Area of interior angles A3 = 893.67 sf Number of P10 portals Np =Total surface area of P10 portals 3617.71 sf **SWAY FRAMES (F)** Top Angle (2 - L5x3.5x7/16; LLH) Top Angle perimeter P1 = 27 in Top angle length L1 = 18.83 ft Surface Area of top angle A1 =508.50 sf Bottom Angle (2 - L5x3.5x7/16; LLH) **Bottom Angle perimeter** P2 = 27 lin Bottom angle length 15.25 ft L2 = Surface Area of bottom angle A2 =411.75 sf Interior Angles (L3.5x3.5x3/8) Interior Angle perimeter P3 =14 in Total interior angle length L3 = 68.50 ft Surface Area of interior angles 959.00 sf A3 =

AMMANN

&

WHITNEY

Project: Grays Ferry Ave Ped Bridge Index No: Subject: Existing Truss Bridge Rehab Quantities Job No: 3061 Designed by: NER Checked by: Date: May 6, 2010 Date: Number of F sway frames Np = Total surface area of F sway frames 3758.50 sf **CENTER PORTALS** Top Angle (2 - L5x3.5x7/16; LLH) Top Angle perimeter P1 = 27 in Top angle length 18.83 ft L1 =Surface Area of top angle 508.50 sf A1 =Bottom Angle (2 - L5x3.5x7/16; LLH) Bottom Angle perimeter P2 = 27 in Bottom angle length L2 = 15.57 ft Surface Area of bottom angle 420.47 sf A2 = Interior Angles (L3.5x3.5x3/8) & k-brace (2 - L3.5x3.5x3/8) Interior Angle perimeter P3 =14 in Total interior angle length L3 = 130.50 ft Surface Area of interior angles 1827.00 sf A3 =Number of center portals Np = Total surface area of center portals 5511.94 sf **TOP LATERALS (T1-T3)** 4 - L3x3.5x5/16 (LLH) with Double Lacing Flange angle perimeter 40 in Ap =Lattice bar length 1.57 ft Lattice bar width 2.25 in wl = Surface area of one lattice bar AI = 0.590 sf Length of lattice bar along lateral L2 = 11.5 in Area of lattice per linear foot of lateral A2 =2.46 sf/ft Total surface area of steel per linear foot of lateral 5.80 sf/ft Number of laterals Nc = 8 Approximate length of top laterals 29.5 ft Total surface area of T1-T3 top laterals 1367.69 sf STAIR FRAME (SF1) and PLATFORM (SP1) 2-C8x13.75 frames with C7x12.25 treads Perimeter of C8x13.75 25.36 in Pf= Length of C8x13.75 Lf = 38.86 ft Surface area of frames Af = 82.134 sf Surface area of platform 10.36 sf Ap =Perimeter of C7x12.25 Pt = 22.76 in Length of one tread 1.99 ft Lt = Number of treads Nt =12 Surface area of treads At = 45.283 sf Nominal surface area for brackets Ab =5.0 sf Total surface area of SF1 frame and treads and SP1 platform and brackets 142.78 sf STAIR FRAME (SF2) and PLATFORM (SP2) 2-C8x13.75 frames with C7x12.25 treads Perimeter of C8x13.75 Pf = 25.36 in Length of C8x13.75 Lf =55.21 ft Surface area of frames 116.674 sf Af =Surface area of platform Ap =31.31 sf Perimeter of C7x12.25 Pt = 22.76 in

& WHITNEY

Length of one tread

AMMANN

1.99 ft

Lt =

5/17/10

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Checked by:

Index No:

Job No: 3061

Date:

Number of treads Surface area of treads

Nominal surface area for brackets

Total surface area of SF2 frame and treads and SP2 platform and brackets

Nt = 24 At = 90.566 sf Ab =10.0 sf 248.55 sf

SUB TOTAL OF SURFACE AREA OF STEEL

ADD 15% FOR GUSSETS, PLATES, CONNECTIONS, ETC.

52414 SF

TOTAL SF OF STEEL TO REHAB ABOVE BOTTOM CHORD

60280

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

Date:

17/10

ADDITIONAL SURFACE AREA REHAB IF TRUSS STAYS IN ORIGINAL POSITION

The following is the calculation of the additional surface area of the steel members below the bottom chord that will need to be rehabilitated if the truss is to stay in place.

WHEEL GIRDER (WG1)

Web depth of constant web depth portion	dc =	60.5	in
Length of constant web depth portion	Lc =	6.5	ft
Average web depth of variable web depth portion	dv =	35.875	in
Length of variable depth portion	Lv =	11.625	ft
Flange width	b =	12.03	in
Total girder length	L =	20.06	ft
Total surface area of WG1 girder		215.51	sf

WHEEL GIRDER (WG2)

Web depth	d = 18 in
Flange width	b = 12.375 in
Girder Length	L = 12.13 ft
Surface Area of one girder	86.39 sf
Number of WG2 girders	Ng = 4
Total surface area of WG2 girders	345.56 sf

PINION GIRDER (PG)

Web depth of constant web depth portion	dc =	68.5 in
Length of constant web depth portion	Lc =	6.5 ft
Average web depth of variable web depth portion	dv =	40 in
Length of variable depth portion	Lv =	11.625 ft
Flange width	b =	12.03 in
Total girder length	L≖	18.13 ft
Total surface area of WG1 girder		224.40 sf

CENTER GIRDERS (CG1 & CG2)

Web depth	d = 60 in
Flange width	b = 14 in
Average Girder Length	L = 21.79 ft
Surface Area of one girder	319.61 sf
Number of CG girders	Ng = 2
Total surface area of WG2 girders	639.22 sf

WEDGE GIRDERS

Web depth	d = 48.5 in
Flange width	b = 9 in
Girder Length	L = 4.50 ft
Surface Area of one girder	49.88 sf
Number of wedge girders	Ng = 4
Total surface area of WG2 girders	199.50 sf

BOLT GIRDERS

d = 39.75
b = 14
L = 4.50
50.81
Ng = 2
101.63

Project: Grays Ferry Ave Ped Bridge

Subject: Existing Truss Bridge Rehab Quantities

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

Date:

6/7/10

TOTAL ADDITIONAL SF OF STEEL BELOW BOTTOM CHORD ADD 15% FOR MISC. MACHINERY CONNECTIONS, PLATES, ETC.

1688 SF 253 SF

TOTAL SF OF STEEL TO REHAB ABOVE & BELOW BOTTOM CHORD

62230 SF

Project: Grays Ferry Ave Ped Bridge

Subject: Masonry Pier & Abutment Rehabilitation

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Date:

Checked by:

AL

05/18/10

The following calculates the approximate total linear feet of Masonry Repointing for the substructures. The stone is assumed to be approximately 2'H x 3'W based on photos. Mean low water is approximately at the

PIERS (EAST & WEST)

Height of stone portion of pier	20.00 ft
Perimeter of pier (approximate average due to batter)	56.26 ft
Approximate height of single stone unit	2.00 ft
Approximate width of single stone unit	5.50 ft
Total LF of vertical repointing	220.00 ft
Total LF of horizontalal repointing	562.64 ft
Total LF of repointing for East & West Pier	1566 ft

CENTER PIER

Height of stone portion of pier	23.00 ft
Perimeter of pier (approximate average due to batter)	90.71 ft
Approximate height of single stone unit	2.00 ft
Approximate width of single stone unit	5.50 ft
Total LF of vertical repointing	391.00 ft
Total LF of horizontalal repointing	1088.56 ft
Total LF of repointing for Center Pier	1480 ft

EAST ABUTMENT

Approximate height of exposed stone portion of abutment Perimeter of exposed abutment (approximate due to limited existing plan info) Approximate height of single stone unit Approximate width of single stone unit Total LF of vertical repointing	11.00 ft 18.00 ft 2.00 ft 5.50 ft 44.00 ft
Total LF of horizontalal repointing	108.00 ft
Total LF of repointing for East Abutment	152 ft

WEST ABUTMENT

Approximate height of exposed stone portion of abutment	30.00 ft
Perimeter of exposed F.F. of abutment (approx. due to limited existing plan info)	44.00 ft
Perimeter of exposed F.F. of wingwalls (approx. due to limited existing plan info)	22.00 ft
Approximate height of single stone unit	2.00 ft
Approximate width of single stone unit	5.50 ft
Total LF of vertical repointing	360.00 ft
Total LF of horizontalal repointing	990.00 ft
Total LF of repointing for West Abutment	1350 ft

TOTAL LF OF REPOINTING 4550 F

Project: Grays Ferry Ave Ped Bridge

Subject: Masonry Pier & Abutment Rehabilitation

Designed by: NER

Date: May 6, 2010

Index No:

Job No: 3061

Checked by:

Date: 05/18/10

The following is a rough approximation for underwater concrete repair. There has been no underwater inspection to assess the current condition of the concrete so there is no accurate measurement of required repair at this point.

Approx. underwater concrete repair for West Pier

Approx. underwater concrete repair for East Pier

Approx. underwater concrete repair for Center Pier

су	0.25
су	0.25
CV	0.50

TOTAL UNDERWATER CONCRETE REPAIR



Project: Grays Ferry Ave Ped Bridge

Subject: Embankment Fill Quantity

Designed by: NER

Date: May 20, 2010

Index No:

Job No: 3061

Checked by:

Date:

The following calculates the approximate total CY of foreign borrow excavation for building the approach embankments

FILL REQUIRED FOR TRUSS CONCEPTS 1 & 2 AND CABLE STAY CONCEPT 2

WEST EMBANKMENT		
Existing ground elevation near abutment	E1 =	28.00
Approximate maximum fill elevation near abutment	E2 =	44.00
Approximate width of west abutment (2 ft greater than super structure width)	w =	14.00 ft
Horizontal component of slope of fill in front of abutment	xf =	2.00
Base width of soil wedge = (E2-E1)*xf	bf =	32.00 ft
Fill required in front of abutment = 0.5*b*(E2-E1)*w	ff =	3584 cf
Horizontal component of slope of fill in back of abutment	xb =	12.00
Base width of soil wedge = (E2-E1)*xb	bb =	192.00 ft
Fill required in front of abutment = 0.5*bb*(E2-E1)*w	fb =	21504 cf
Average height of soil wedges on side of abutment = (E2-E1)/2	hs =	8.00 ft
Fill required on side of abutment = 2*0.5*hs*(bf+bb)*bf	fs =	57344 cf
EAST EMBANKMENT		
E de la company de la constante de la constant		22.22

Existing ground elevation near abutment	E1 =	28.00
Approximate maximum fill elevation near abutment	E2 =	47.00
Approximate width of west abutment (2 ft greater than super structure width)	w =	14.00 ft
Horizontal component of slope of fill in front of abutment	xf =	2.00
Base width of soil wedge = (E2-E1)*xf	bf =	38.00 ft
Fill required in front of abutment = 0.5*b*(E2-E1)*w	ff =[5054 cf
Horizontal component of slope of fill in back of abutment	xb =	12.00
Base width of soil wedge = (E2-E1)*xb	bb =	228.00 ft
Fill required in front of abutment = 0.5*bb*(E2-E1)*w	fb =[30324 cf
Average height of soil wedges on side of abutment = (E2-E1)/2	hs =[9.50 ft
Fill required on side of abutment = 2*0.5*hs*(bf+bb)*bf	fs =[96026 cf

FILL REQUIRED FOR TRUSS CONCEPT 3 AND CABLE STAY CONCEPT 1

WEST EMBANKMENT Existing ground elevation near abutment Approximate maximum fill elevation near abutment Approximate width of west abutment (2 ft greater than super structure width) Horizontal component of slope of fill in front of abutment Base width of soil wedge = (E2-E1)*xf Fill required in front of abutment = 0.5*b*(E2-E1)*w	E1 = 28.00 E2 = 36.00 w = 14.00 ft xf = 2.00 bf = 16.00 ft ff = 896 cf
Horizontal component of slope of fill in back of abutment Base width of soil wedge = (E2-E1)*xb Fill required in front of abutment = 0.5*bb*(E2-E1)*w	xb = 12.00 bb = 96.00 ft fb = 5376 cf
Average height of soil wedges on side of abutment = (E2-E1)/2 Fill required on side of abutment = 2*0.5*hs*(bf+bb)*bf	hs = 4.00 ft fs = 7168 cf

EAST EMBANKMENT

TOTAL CY OF FILL REQUIRED

Existing ground elevation near abutment	
Approximate maximum fill elevation near abutment	
Approximate width of west abutment (2 ft greater than super structure width)	

7920 CY

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: Embankment Fill Quantity Job No: 3061 Designed by: NER Checked by: 8/21/10 Date: May 20, 2010 Date: Horizontal component of slope of fill in front of abutment 2.00 xf = Base width of soil wedge = (E2-E1)*xf bf =22.00 ft Fill required in front of abutment = 0.5*b*(E2-E1)*w ff = 1694 cf Horizontal component of slope of fill in back of abutment xb =12.00 Base width of soil wedge = (E2-E1)*xb bb =132.00 ft Fill required in front of abutment = 0.5*bb*(E2-E1)*w 10164 cf fb =Average height of soil wedges on side of abutment = (E2-E1)/2 5.50 ft hs = Fill required on side of abutment = 2*0.5*hs*(bf+bb)*bf fs = 18634 cf **TOTAL CY OF FILL REQUIRED** 1628 CY

Project: Grays Ferry Ave Ped Bridge

Subject: New Pier & Abutment Construction Cost

Designed by: NER

Date: May 19, 2010

Index No:

Job No: **3061**

Checked by:

Date:

6/30/10

The following calculates the approximate total CY of concrete and LBS of steel for the construction of the new abutments and portions of piers. Assume substructure length perpendicular to C.L. of roadway will be 2'-0" wider than the superstructure width in order to provide sufficient bearing area. Assume required reinforcement is 200 LBS per CY of concrete for piers and 90 LBS per CY of concrete for abutments, which was approximated from sample projects. Assume new concrete portions will be doweled into existing with 18" deep dowels at 12" spacing

EAST & WEST STUB ABUTMENTS (Required for all concepts)

The dimensions calculated below are approximated from PennDOT BC-799M standard for MSE Abutments

Height of abutment (Assume 3' for bearing inspection plus 3' min frost cover)

Width of abutment
Length of abutment
Height of backwall
Width of backwall
Length of backwall
Total CY of Concrete for East & West Abutments

6.00 ft
14.00 ft
11.00 ft
11.00 ft
11.00 ft

Total LBS of Reinforcement for East & West Abutments 2070 LBS

**Assume each stub abutment is supported on 4 - HP12x53 piles (each having a 50 ft length)

Total LF of HP pile

400 ft

EAST & WEST PIERS, 35 ft HEIGHT (Required for Truss Concept 3 & Cable-Stay Concepts 1 23

Height of pier

Width of pier

Uidth of pier

State of the state of th

Total LBS of Reinforcement for 35 ft High East & West Piers 21800 LBS

Total number of dowels for East and West Piers 66

EAST & WEST PIERS, 45 ft HEIGHT (Required for Truss Concepts 1 & 2)

Height of pier 45.00 ft Width of pier 3.00 ft Length of pier 14.00 ft

Total CY of Concrete for 45 ft High East & West Piers 140 CY

Total LBS of Reinforcement for 45 ft High East & West Piers

28000 LBS

Total number of dowels for East and West Piers 66

CENTER PIER, 35 ft HEIGHT (Required for Truss Concept 3 & Cable-Stay Concept 1)

Height of pier
Width of pier
Length of pier
Length of pier

Total CY of Concrete for 35 ft High Center Pier

Total LBS of Reinforcement for 35 ft High Center Pier

Total number of dowels for Center Pier

55 CY

Total number of dowels for Center Pier

66

CENTER PIER, 45 ft HEIGHT (Required for Truss Concept 1)

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: New Pier & Abutment Construction Cost Job No: 3061 Designed by: NER Checked by: 6/30/10 Date: May 19, 2010 Date: Height of pier 45.00 ft Width of pier 3.00 ft Length of pier 14.00 ft Total CY of Concrete for 45 ft High Center Pier 70 CY Total LBS of Reinforcement for 35 ft High Center Pier 14000 LBS Total number of dowels for Center Pier 66 **ABUTMENT & PIER CAP RECONSTRUCTION** Assume bearing area of the substructure is reconstructed with a 2 ft high cap with the same plan area as the existing abutment and piers. Assume required reinforcment is 90 LBS per CY of concrete for abutment and pier East Abutment (Required for Cable-Stay Concepts 1 & 2) Height of cap 2.00 ft Width of cap 6.00 ft Length of cap 26.67 ft Volume of cap 12 CY Total LBS of Reinforcement for East Abutment 1067 LBS Total number of dowels for East Abutment 64 West Abutment (Required for Cable-Stay Concepts 1 & 2) Height of cap 2.00 ft Width of cap 6.00 ft Length of cap 50.00 ft

Volume of cap

Height of cap

Width of center portion of cap

Length of center portion of cap

Volume of East & West Pier cap

Width of triangular end portion of cap

Length of triangular end portion of cap

Total LBS of Reinforcement for West Abutment

East & West Pier (Required for Cable-Stay Concepts 2 & 3)

Total number of dowels for West Abutment

22 CY

2000 LBS

110

2.00 ft

7.67 ft

25.00 ft

7.67 ft

3.83 ft

31 CY

AMMANN & WHITNEY Project: Grays Ferry Ave Ped Bridge Index No: Subject: New Pier & Abutment Construction Cost Job No: 3061 Designed by: NER Checked by: Date: May 19, 2010 Date: 6/30/10 Total CY for Abutment and Pier Cap Reconstruction for Cable-Stay Concept 2 117 CY Total LBS of reinf. for Abutment and Pier Cap Recon. For Cable-Stay Concept 2 10452 LBS Total 18" Dowel Holes for Abutment and Pier Cap recon. For Cable-Stay Concept 2 398 Total CY for Abutment and Pier Cap Reconstruction for Cable-Stay Concept 3 31 CY Total LBS of reinf. for Abutment and Pier Cap Recon. For Cable-Stay Concept 3 2751 LBS Total 18" Dowel Holes for Abutment and Pier Cap recon. For Cable-Stay Concept 3 130 TRUSS CONCEPT 1 **Total CY of Concrete** 233 CY Total LBS of Reinforcement 44070 LBS Total number of 18" Dowel Holes 132 **TRUSS CONCEPT 2 Total CY of Concrete** 163 CY **Total LBS of Reinforcement** 30070 LBS Total number of 18" Dowel Holes 66 **TRUSS CONCEPT 3 Total CY of Concrete** 187 CY **Total LBS of Reinforcement** 34870 LBS Total number of 18" Dowel Holes 132 **CABLE-STAY CONCEPT 1 Total CY of Concrete** 222 CY **Total LBS of Reinforcement** 37937 LBS Total number of 18" Dowel Holes 306 **CABLE-STAY CONCEPT 2 Total CY of Concrete** 140 CY **Total LBS of Reinforcement** 12522 LBS Total number of 18" Dowel Holes 398 **CABLE-STAY CONCEPT 3 Total CY of Concrete** 163 CY

Total LBS of Reinforcement

Total number of 18" Dowel Holes

26621

196

LBS

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 1 Preliminary Design

Designed by: AL

Date: June 4, 2010

Index No:

Job No: 3061

Checked by: NER

Date: 6/29/10


References


- AASHTO Standard Specifications, 15th Edition, 1992.

Description	<u>Symb</u>	Value	<u>Unit</u>	<u>Reference</u>
Deck Section Length	S	28.00	FT	
Bridge DL /ft	W	1.37	KLF	See deck calculation spreadsheet
Bridge LL /ft	р	0.85	KLF	
Nbr of Cables / Section	n	2.00		Two planes of cables
Service dead load / Cable	TLdl	19.18		
Service live load / Cable	TLII	11.90	K	= (w + p) * S / n

	α	β	Tdl=TLdl / sin(α)	TII=TLII / sin(α)	Total Cable Tension	2*(1.3*Tdl+ 2.17*Tll) * cos(β)
Cable 1	38.32	51.67	30.93	19.19	50.12	101.54
Cable 2	44.78	45.20	27.23	16.89	44.12	101.55
Cable 3	55.65	34.33	23.23	14.41	37.65	101.54
Cable 4	75.32	14.68	19.83	12.30	32.13	101.51

Factored mast force = Σ 2 Ti cos(β i) = **406.14** KIPS





Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 1 Preliminary Design

Designed by: AL

Date: June 4, 2010

Index No:

Job No: 3061

Checked by: NFR

Date:6/29/10

Cable Design

Description Working load per strand: Nbr of strands required mber of cables required / mast Cable 1 Length Cable 2 Length Cable 3 Length Cable 4 Length Total length per span Total length for bridge	Symb Fkn Fk Ns Nc	Value 125.58 28.23 3.90 16 249.86 197.26 148.92 110.58 1413.24 2826.48	Unit KN KIPS FT FT FT FT FT	Reference 1507 KN / 12 strands (SYWIDAG Systems Brochure)
Mast Design				
Yield strength Modulus of Elasticity Height of Mast Section Dimension Wall thickness X-Sectional area Inertia Sectional Modulus Radius of Gyration Slenderness Coefficient	Fy E H a t Am Im Sm r K	50.00 29000.00 77.50 33.50 0.75 98.25 17572.42 1049.10 13.37 2.00 139.08	KSI KSI FT IN IN^2 IN^4 IN^3	Masts are assumed to be braced at deck level = (a^4 - (a - t) ^4 / 12 = Im / (a/2) = (Im / Am) ^ 1/2 = K * H / r^2
Buckling stress Capacity of Mast Check adequacy	Cc Fcr Pcr	107.00 14.80 421.34 ADEQUATE	KSI KIPS	= (2 * pi^2 * E / Fy) ^1/2 Eqns 10-151 & 10-153 AASHTO = 0.85 * Am * Fcr

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 1 Preliminary Cost Estimate

Designed by: AL

Date: June 4, 2010

3061

NER 6/29/10

CABLE INCLUDING PROTECTION

Description	<u>Value</u>	<u>Unit</u>	<u>Reference</u>
Cable 1 Length	249.86	FT	
Cable 2 Length	197.26	FT	
Cable 3 Length	148.92	FT	
Cable 4 Length	110.58	FT	

There are 4 cables for each of the lengths presented above

MASTS

Height	Htot	113.75	FT	
X-sectional area at base	Am	98.25	IN ²	
X-Sectional area at top	Am2	58.95	IN ²	Assumed 60% of base
Number of masts	Nm	4.00		
Weight of masts	Wm	121693.54	LBS	
Weight of deck brace		6686.46	LBS	Assumed same section as mast
Total Fab Struct Steel		128380.00	LBS	and 10 ft length

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 2 Preliminary Design

Designed by: AL

Date: June 4, 2010

Index No:

Job No: **3061**

Checked by: NER

Date: 6/29/10

References

- AASHTO Standard Specifications, 15th Edition, 1992.

Description	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	<u>Reference</u>
Deck Section Length	S	20.00	FT	
Bridge DL /ft	W	1.37	KLF	See deck calculation Mathcadsheet
Bridge LL /ft	р	0.85	KLF	
Nbr of Cables / Section	n	2.00		Two planes of cables
Service dead load / Cable	TLdl	13.70		
Service live load / Cable	TLII	8.50	K	= (w + p) * S / n

	α	β	Tdl=TLdl/si n(α)	TII=TLII/sin (α)	Total Cable Tension
Cable 1	42.50	72.97	20.28	12.58	32.86
Cable 2	52.52	62.93	17.26	10.71	27.97
Cable 3	69.37	46.10	14.64	9.08	23.72

Cable Design Force, assuming FS=2.2

= Tmax * 2.2 =

72.29

Kips

Say **75**

KIPS

Cable Design

Description Working load per strand: Nbr of strands required Number of cables required Cable 1 Length Cable 2 Length Cable 3 Length Total length per span	Symb Fkn Fk Ns Nc	Value 125.58 28.23 2.66 12.00 136.00 106.00 80.00	Unit KN KIPS FT FT FT FT	Reference 1507 KN / 12 strands (SYWIDAG Systems Brochure)
Total length per span Total length for bridge		644 2576	FT FT	
<u>Mast Design</u>				
Deck Length	L	120.00	FT	

Deck Length	L	120.00	FT	
Total Deck Dead Load	DL	164.4	KIPS	= L * w
Total Deck Live Load	LL	102	KIPS	= L * p
Moment due to 1 KIP	My+	0.00	K-FT	Larsa analysis
Moment due to 1 KIP	My-	0.01	K-FT	Larsa analysis
Axial Force du to 1 KIP	FX	0.58	KIPS	Larsa analysis

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 2 Preliminary Design

Designed by: **AL**

Date: June 4, 2010

Index No:

Job No: 3061

Checked by: NEK

Date: 6/2a/10

Page : 2 of 2

Printed: 6/29/2010 - 4:47 PM

Factored Axial Force in I	_eg
Factored +Moment in I	_eg
Factored -Moment in I	ea

2	51.03	KIPS
	0.00	K-FT
	3.48	K-FT

Since the moments are so small, design for axial force only.

Yield strength Modulus of Elasticity Length of Leg Section Dimension Wall thickness X-Sectional area Inertia Sectional Modulus Radius of Gyration Slenderness Coefficient	Fy E H a t Am Im Sm r K	50.00 29000.00 102.00 28.50 0.75 83.25 10692.42 750.35 11.33 1.50	KSI KSI FT IN IN IN^2 IN^4 IN^3 IN	= (a^4 - (a - t)^4 / 12 = Im / (a/2) = (Im / Am) ^ 1/2 Buckling factor is reduced from 2.0 to account for mutual bracing between legs. = K * H / r
Buckling stress Capacity of Mast Check adequacy	Cc Fcr Pcr	107.00 10.91 264.18 ADEQUATE	KSI KIPS	= (2 * pi^2 * E / Fy) ^ 1/2 Eqns 10-151 & 10-153 AASHTO = 0.85 * Am * Fcr

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable Concept 2 Preliminary Cost Estimate

Job No: 3061

Page : 1 of 1

Printed: 6/29/2010 - 5:54 PM

Designed by: AL

Checked by:

Date: June 4, 2010

Date:

CABLE INCLUDING PROTECTION

Description	<u>Value</u>	<u>Unit</u>	<u>Reference</u>
Cable 1 Length	136.00	FT	
Cable 2 Length	106.00	FT	
Cable 3 Length	80.00	FT	

There are 8 cables for each of the lengths presented above

MASTS

INIAO I O				
Height	Htot	102.00	FT	
X-sectional area at base	Am	83.25	IN^2	
X-Sectional area at top	Am2	49.95	IN^2	Assumed 60% of base
Number of masts	Nm	8.00		
Weight of masts	Wm	184926.00	LBS	
Weight of deck brace		46741.41	LBS	Assumed same section as mast
Total Fab Struct Steel		231667.41	LBS	and 33 ft length

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable-Stay Concept 3 Preliminary Design

Designed by: AIS

Date: June 24, 2010

Index No:

Job No: 3061

Checked by: NER

Date: 6 /29 /10

References

AASHTO Standard Specifications, 15th Edition, 1992.

Geometry and Preliminary Loads

<u>Description</u>	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	Reference
Deck Section Length	S	22.63	FT	Measured from CADD
Bridge DL / ft	W	1.37	KLF	See deck calculation Mathcad sheet
Bridge LL / ft	р	0.85	KLF	See deck calculation Mathcad sheet
Nbr of Cables / Section	n	2		Two planes of cables
Service dead load / Cable	TLdl	15.50	KIPS	= w*S / n
Service live load / Cable	TLII	9.62	KIPS	= p*S / n

	α	β = 90-α	$Tdl = TLdl/sin(\alpha)$	TII = $TLII/sin(\alpha)$	Total Cable Tension	2 * (1.3*Tdl + 2.17*Tll) * cos(β)
Cable 1	34.18	55.82	27.59	17.12	44.71	82.05
Cable 2	36.06	53.94	26.33	16.34	42.67	82.05
Cable 3	39.15	50.85	24.55	15.23	39.79	82.05
Cable 4	45.05	44.95	21.90	13.59	35.49	82.05
Cable 5	58.53	31.47	18.17	11.28	29.45	82.05

Factored mast force = 410.23 KIPS

<u>Description</u>	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	<u>Reference</u>	
Max cable tension	Tmax	44.71	KIPS	Max from above table	
Factor of safety	FS	2.20		Assumed	
Cable design force	Fcable	99	KIPS	= Tmax * FS	(Roundup)

Cable Design

<u>Description</u>	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	<u>Reference</u>
Working load per strand	Fstrand	28.23	KIPS	DYWIDAG brochure (1507-KN per 12-strands)
Nbr of strands required	Ns	3.51		= Fcable / Fstrand
Number of cables required	Nc	20.00		See drawings
Cable 1 Length	L1	124.00	FT	Measured from CADD
Cable 2 Length	L2	100.00	FT	Measured from CADD
Cable 3 Length	L3	74.00	FT	Measured from CADD
Cable 4 Length	L4	48.00	FT	Measured from CADD
Cable 5 Length	L5	20.00	FT	Measured from CADD
Total length per span	Lspan	732	FT	= 2 * (ΣLi)
Total length for bridge	Lbridge	2928	FT	= Lspan *4

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable-Stay Concept 3 Preliminary Design

Designed by: AIS

Date: June 24, 2010

Index No:

Job No: **3061**

Checked by: NEW

Date: 6

Mast Design

Yield strength Modulus of Elasticity Length of Leg Section Dimension Wall thickness X-Sectional area Inertia Sectional Modulus Radius of Gyration Slenderness ratio	Fy E H a t Am Im Sm r K	50.00 29,000 75.00 33.00 0.75 96.75 16780.08 1016.97 13.17 2.00 136.68	KSI KSI FT IN IN IN^2 IN^4 IN^3 IN	Material property Material property Masts assumed to be braced at deck level Assumed Assumed = a^2 - (a-2t)^2 = (a^4 - (a - t)^4 / 12 = Im / (a/2) = (Im / Am) ^ 1/2 Assumed = K * H / r^2
Buckling stress Capacity of Mast	Cc Fcr Pcr	107.00 15.32 429.76	KSI KIPS	= (2 * pi^2 * E / Fy) ^ 1/2 Eqns 10-151 & 10-153 AASHTO = 0.85 * Am * Fcr

Check adequacy: ADEQUATE

Project: Grays Ferry Avenue Pedestrian Bridge

Subject: Cable-Stay Concept 3 Quantities

Designed by: AIS

Date: June 25, 2010

Index No:

Job No: **3061**

Checked by: NER

Date: 6/30/10

Cables

NOTE: Installation and anchorages and protection is included and will be taken as a lump sum item

<u>Description</u>	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	Reference
Total length of cables	Lcab	2928.00	FT	From design worksheet

Masts

Description	<u>Symb</u>	<u>Value</u>	<u>Unit</u>	Reference
Total height X-sectional area at bottom X-Sectional area at top Number of masts Weight of masts Weight of deck brace Total Fab Struct Steel	Htot Atop Abot Nm Wm Wb	115.00 96.75 58.05 4.00 121,152.50 32,592.66 153,745.16	FT IN^2 IN^2 LBS LBS	Measured from CADD From design worksheet Assume 60% of bottom dimension From drawings =Nm*Htot(Atop+Abot)/2/144 * 490-pcf Assume 33-ft length and same section as mast (x2 braces) =Wb+Wm

Project: Grays Ferry Pedestrian Bridge

Subject: Stringer Design

Designed by: **NER** Date: **June 9, 2010**

Index No:

Job No: 3061

Checked by: Date: AL 19/10

The following is a rough design for the stringer design of a pedestrian cable stay bridge. The purposed of the design at this point is to get numbers for estimating cost of the superstructure and cables.

Stringer Design

Dead Load

Deck

$$t_d := 5.5in$$

$$\gamma_c := 0.15 \left(\frac{\text{kip}}{\text{ft}^3} \right)$$

$$SIP := 0.015 \frac{kip}{ft^2}$$

$$D_{DL} := t_d \cdot \gamma_c + SIP = 0.08 \cdot ksf$$

Thickness of deck

Curb

$$t_c := 4in$$

$$C_{DL} := \gamma_c \cdot t_c \cdot w_c = 0.05 \cdot \frac{kip}{ft}$$

Approximate thickness of

Railing

$$R_{DL} := 0.05 \frac{\text{kip}}{\text{ft}}$$

Beam Weight

$$S_{DL} := 0.1 \frac{kip}{ft}$$

$$B_{DL} := 0.25 \cdot S_{DL} = 0.03 \cdot klf$$

Approximate self weight of

Project: Grays Ferry Pedestrian Bridge

Subject: **Stringer Design** Designed by: **NER**

Designed by: **NER** Date: **June 9, 2010**

Index No:

Job No: **3061** Checked by:

Date:

AL 6/9/10

Total Dead Load and Dead Load Moments on Stringer

$$DL := D_{DL} \cdot \frac{s}{2} + S_{DL} + B_{DL} = 0.59 \cdot klf$$

Total DL on stringer

$$SDL := C_{DL} + R_{DL} = 0.10 \cdot klf$$

Total superimposed DL on

stringer

Distance between cable stays (stringer supports)

$$M_{DL} := 0.16 \cdot DL \cdot cs^2 = 73.46 \cdot ft \cdot kip$$

Dead Load moment (AISC Manual 2nd Edition - Beam Diagrams and Formulas Continuous Beams)

$$M_{SDL} := 0.16 \cdot SDL \cdot cs^2 = 12.54 \cdot ft \cdot kip$$

Superimposed Dead Load moment (AISC Manual 2nd Edition - Beams Diagrams and

Formulas Continuous Beams)

Live Load

Pedestrian Live Load

$$LL_{ped} := .085 \frac{kip}{ft^2}$$

Pedestrian Live Load


Rw := 10ft

Roadway width

$$M_{LLped} := 0.16 \cdot \left(LL_{ped} \cdot \frac{Rw}{2} \right) \cdot cs^2 = 53.31 \cdot ft \cdot kip$$

Pedestrian Live Load moment

H5 Vehicular Live Load



Axle Loads

Based on engineering judgement, the pedestrian live load will govern the stringer design, therefore vehicular live load moment was not calculated.

Project: Grays Ferry Pedestrian Bridge

Subject: Stringer Design

Designed by: NER
Date: June 9, 2010

Index No:

Job No: **3061** Checked by:

Date:

AL 6/9/10

ASD Check

*Assume non-composite section

$$M_{max} := M_{DL} + M_{SDL} + M_{LLped} = 139.32 \cdot ft \cdot kip$$

Total maximum moment

$$f_y := 50 \frac{\text{kip}}{\text{in}^2}$$

Yield strength of steel

$$S_{reqd} := \frac{M_{max}}{\left(o.55 \cdot f_y\right)} = 60.79 \cdot in^3$$

Minimum required section

modulus

Try W12x50

$$S_0 = 64.2 in^3$$

$$S_n = 105.8 in^3$$

$$S_{3n} := 94.2 \text{in}^3$$

See attached Girder Section Properties calc sheet

Properties calc sheet

LFD Check

$$\sigma_b := \left(1.3 \cdot \frac{M_{DL}}{S_o}\right) + \left(1.3 \cdot \frac{M_{SDL}}{S_{3n}}\right) + \left(2.17 \cdot \frac{M_{LLped}}{S_n}\right) = 33.05 \cdot ksi$$

Check_{LFD} := $if(\sigma_b \le f_v, "FLEXURE OK", "FLEXURE NG") = "FLEXURE OK"$

Total Bridge Loads for Cable Stay Design

$$W_{DL} := 2 \cdot (DL + SDL) = 1.37 \cdot klf$$

Total Bridge Dead Load/ft

$$w_{LL} := LL_{ped} \cdot Rw = 0.85 \cdot klf$$

Total Bridge Live Load/ft

COMP BY NER

DATE 6/9/10 DATE 6/9/10

PROJECT Grays Ferry Ave Pedestrian Bridge subject Stringer Gross Section Properties SHT NO

ЈОВ NO 3061

STEEL GIRDER SECTION PROPERTIES CALCULATION

	Eff Flange Width Calc					
	Top PI Eff	Top Flg Eff.	Bot Flg Eff	Bot Pl Eff		
Comp or Ten	С	С	T	T		
Flg W	0.000	8.080	8.080	0.000	in	
Flg T	0.000	0.640	0.640	0.000	in	
Bolt Dia	0.000	0.000	0.000	0.000	in	
# of Bolts	0	0	0	0		
Hole Dia	0.000	0.000	0.000	0.000	in	
EFF Width	0.00	8.08	8.08	0.00	in	

NOTES: A10.16.14.6 Use hole dia as 1/8" greater than bolt dia.
A10.18.1.1 Compression member use Ag
A10.18.1.1 Ae is amount above 15% removed from Ag

	Slab Eff V	Vidth Calc	
Span Length	28,00	ft	
Beam Spa	11.00	ft	AASHTO
OverHang W	0.00	ft	10.38.1
1/4 SL	84.00	in	
Bm Span	132.00	in	
12*ts	66.00	in	= beff

SECTION DIMENSIONS

	Width (in)	Height (in)*
Deck	66.00	5.5
Haunch	-	0
Top Plate	0.000	0.000
Top Flange	8.080	0.640
Web	0.370	10.920
Bot Flange	8.080	0.640
Bot Plate	0.000	0.000
n	8,000	

- from top of deck to to top of beam

COMPONENT SECTION PROPERTIES - NONCOMPOSITE

AXIS X-X	Area (in²)	Yx(m)	Ix (in ⁴)
Top Plate	0.000	6.100	0.00
Top Flange	5.171	5.780	172.94
Web	4.040	0.000	40.15
Bot Flange	5.171	5.780	172.94
Bot Plate	0.000	6.100	0.00

AXIS Y-Y	Area (m²)	Yy(m)	Iy (m ⁴)
Top Plate	0.000	0.000	0.00
Top Flange	5.171	0.000	28.13
Web	4.040	0.000	0.05
Bot Flange	5.171	0.000	28.13
Bot Plate	0.000	0.000	0.00

COMPONENT SECTION PROPERTIES - COMPOSITE

AXIS X-X	Area (in²)	Yx(m)	Ix (in ⁴)
Deck (3n)	15.125	14.950	38.13
Deck (n)	45.375	14.950	114.38
Top Plate	0.000	12.200	0.00
Top Flange	5.171	11.880	0.18
Web	4.040	6.100	40.15
Bot Flange	5,171	0.320	0.18
Bot Plate	0.000	0.000	0.00

40 Y **DECK** 20 X X -20 20 Y Cross Section of Beam w/ NA Located

GIRDER SECTION PROPERTIES

No	on-Composite		
	Axis X-X		
Ag	14.38 in ²		
Ix	386 in ⁴		
Stx	63.3 in ³		
Sbx	63.3 in ³		
ytx	6.10 in		
ybx	6.10 in		
rx	5.18 in		
Zx	70.81 in ³		

	Axis X-X
Ag	29.51 in ²
Ix	1002 in ⁴
Sty	640.5 in ³
Sby	94.2 in ³
ytx	1.56 in
ybx	10.64 in

No	n-Composite	
Axis Y-Y		
Ag	14.38 in ²	
Iy	56 in ⁴	
Sty	9.2 in ³	
Sby	9.2 in ³	
yty	0.00 in	
yby	0.00 in	
ry	1.98 in	

Composite n Axis X-X	
Ix	1356 in⁴
Sty	-2187.0 in ³
Sby	105.8 in ³
ytx	-0.62 in
ybx	12.82 in

Printed: 6/10/2010 8:18 AM

Project: Grays Ferry Ave Ped Bridge

Subject: Steel and Concrete for Cable-Stay Superstructures

Designed by: NER

Date: June 10, 2010

Index No:

Job No: 3061

Checked by: AL

Date: 07/06/10

The following calculates the approximate weight of steel, volume of concrete and weight of reinforcement required for the proposed Cable-Stay Concept's 1 & 2 superstructures.

CABLE-STAY CONCEPT - 1

STEEL (Stringers, Floorbeams & Bracing)	
Lipport weight of stringer (M/12yEO) (See stringer decise)	

Linear weight of stringer (vv 12x50) (See stringer design)	
Total length of stringer	
Total weight of stringer	,
Total weight of bracing (Assume 20% of stringer weight)	1
Linear weight of floorbeam (Conservatively assume same as stringer)	
Total length of floorbeam (One at each stay) (16 stays x 13')	
Total weight of floorbeam	

49640 LBS

50.0 plf

654.0 ft

32700 lbs

6540 lbs

50.0 plf

208.0 ft

10400 lbs

ws = Ls =

SW =

BW =

wf =

Lf =

FW =

CONCRETE (Deck & Curb)

Width of Deck	wd = 12.0 ft
Thickness of Deck	td = 0.46 ft
Length of Deck	Ld = 554.0 ft
Width of Curb	wc = 1.0 ft
Height of Curb	hc = 0.33 ft
Total cubic feet of concrete	vc = 3416 cf

Total LBS of steel for Cable-Stay Concept - 1 Superstructure

REINFORCEMENT (Deck & Curb)

Total LBS of reinforcement for Cable-Stay Concept - 1 Superstructure

25400	IRS

127 CY

CABLE-STAY CONCEPT - 2

STEEL (Stringers, Floorbeams & Bracing)

Linear weight of stringer (W12x50) (See stringer design)	ws =	50.0	plf
Total length of stringer	Ls =	1108.5	ft
Total weight of stringer	SW =	55425	lbs
Total weight of bracing (Assume 20% of stringer weight)	BW =	11085	lbs
Linear weight of floorbeam (Conservatively assume same as stringer)	wf =	50.0	plf
Total length of floorbeam (Assume 8 stays for main span) (24 stays x 13')	Lf =	312.0	ft
Total weight of floorbeam	FW =[15600	lbs
Total LBS of steel for Cable-Stay Concept - 2 Superstructure		82110	LBS

CONCRETE (Deck & Curb)

Width of Deck Thickness of Deck Length of Deck Width of Curb	wd = td = Ld = wc =	12.0 ft 0.46 ft 554.3 ft 1.0 ft
Height of Curb Total cubic feet of concrete Total CY of concrete for Cable-Stay Concept - 2 Superstructure	hc = [vc = [0.33 ft 3418 cf
Total OT of concrete for Cable-Stay Concept - 2 Superstructure		127 CY

REINFORCEMENT (Deck & Curb)

Total LBS of reinforcement for Cable-Stay Concept - 2 Superstructure

25400 LBS

^{*}Assume required deck reinforcement is 200 lbs per CY of concrete

^{*}Assume required deck reinforcement is 200 lbs per CY of concrete

Project: Grays Ferry Ave Ped Bridge

Subject: Steel and Concrete for Cable-Stay Superstructures

Designed by: NER

Date: June 10, 2010

Index No:

Job No: 3061

Checked by: AL Date: 07/06/10

CABLE-STAY CONCEPT - 3

*This concept is esentially the same as concept-1 with the emilination of reusing the existing truss

STEEL (Stringers, Floorbeams & Bracing)

Linear weight of stringer (W12x50) (See stringer design)	ws =	50.0 plf
Total length of stringer	Ls =	843.6 ft
Total weight of stringer	SW =	42181 lbs
Total weight of bracing (Assume 20% of stringer weight)	BW =	8436 lbs
Linear weight of floorbeam (Conservatively assume same as stringer)	wf =	50.0 plf
Total length of floorbeam (Assume 8 stays for main span) (20 stays x 13')	Lf =	260.0 ft
Total weight of floorbeam	FW =	13000 lbs

Total LBS of steel for Cable-Stay Concept - 2 Superstructure

63618	1	RS

CONCRETE (Deck & Curb)

Width of Deck	wd = 12.0 ft
Thickness of Deck	td = 0.46 ft
Length of Deck	Ld = 421.8 ft
Width of Curb	wc = 1.0 ft
Height of Curb	hc = 0.33 ft
Total cubic feet of concrete	vc = 2601 cf

Total CY of concrete for Cable-Stay Concept - 2 Superstructure

97	CY
0,	•

REINFORCEMENT (Deck & Curb)


*Assume required deck reinforcement is 200 lbs per CY of concrete


Total LBS of reinforcement for Cable-Stay Concept - 2 Superstructure


19400 LBS


APPENDIX D

(Roadway Plans)









APPENDIX E

(Project Site Photographs)

Grays Ferry Pedestrian Bridge Conceptual Design Report (DCNR Project No. BRC-TAG-14-240)




Figure 1: Looking East at Existing Swing Truss Bridge




Figure 2: Looking North at Existing Swing Truss Bridge and Grays Ferry Avenue Highway Bridge

Grays Ferry Pedestrian Bridge Conceptual Design Report (DCNR Project No. BRC-TAG-14-240)



Figure 3: Looking at East Bank from Grays Ferry Avenue Highway Bridge



Figure 4: Looking at West Bank from Grays Ferry Avenue Highway Bridge

Grays Ferry Pedestrian Bridge Conceptual Design Report (DCNR Project No. BRC-TAG-14-240)




Figure 5: Looking West at Existing Swing Truss Bridge




Figure 6: Looking West at South End of Open Truss (Deteriorated Fender System)

APPENDIX F

(Public Involvement)



November 16, 2009

to: Invitees, File from: Lane Fike, P.E.

re: Grays Ferry Pedestrian Bridge – Feasibility Study

Stakeholder Committee Meeting – Nov. 12, 2009–1:30 to 3:00

Philadelphia Trolley Works - Conference Room

Invitees:

• Louise Turan, Bartrams Garden

- Michael Kates, Philadelphia Trolley Works (PTW)
- Sarah Clark Stuart, SRPA & Bicycle Coalition
- Karen Cilurso, DVRPC
- Deborah Schaaf, PCPC
- Jon Edelstein, City Commerce Dept. unavailable
- Donna Henry, SWCDC unavailable
- Lane Fike, SRDC
- o Joseph Syrnick, SRDC
- o Joe Sullivan, Ammann & Whitney
 - Stakeholder Committee Member

After introductions of all attendees, Joe Syrnick summarized the goals of SRDC and the projects currently underway. The major goal is to revitalize the Tidal or Lower Schuylkill River. This includes improved access to the river and the extension of the trail to Bartrams Garden. Current projects included the Grays Ferry Crescent which could be bid in December. That project would serve as a gateway to the Grays Ferry Pedestrian Bridge. Syrnick explained that SRDC used its approved consultant selection process to select Ammann & Whitney to perform the conceptual study.

Joe Sullivan then outlined the issues and options (see attached Agenda) for the river crossing and distributed drawings and photos. Critical parameters include the need to provide passage of river traffic, ensure compliance with ADA and meet the physical restraints of the site. The required vertical clearance has yet to be determined. Because of the reduction in river traffic, a reduced clearance could allow for a lower deck for the proposed bridge. As part of its scope of work, A&W will determine the vertical clearances and permitting required, with the assistance of McCormick Taylor. They have engaged AWK to perform the physical survey. It was indicated that retention of the existing railroad truss could be a desirable goal for the project. Reuse of the substructure to support the new superstructure could ease permitting and construction costs and be an interesting adaptive re-use of an existing structure.

Mike Kates suggested that the use of a ferry could be cost effective and eliminate the need to deal with clearance issues. Syrnick asked Kates to provide a rough cost estimate

of a ferry service for consideration. Kates also suggested the use of the active CSX swing bridge south of the proposed crossing. This can be pursued with CSX.

Sarah Stuart asked about a low structure that could be possibly supported on pontoons and opened for passage of large river traffic. She also suggested that a representative of the Forgotten Bottom neighborhood be invited into the review process.

Karen Cilurso asked that SRDC supply documentation of their consultant selection process to DVRPC.

It was agreed that once the physical survey is complete, the vertical clearance requirements are better defined and other options are investigated, the committee would meet again to discuss how to advance the project.





Sept. 27, 2010

to: Invitees, File from: Lane Fike, P.E.

re: Grays Ferry Crossing Trail Bridge

Crossing Concept Committee Meeting

Sept. 27, 2010 9am to 12 pm Trolley Works Conf. Room

Invitees:

CCC - Louise Turan, Exe. Dir., Bartrams Debbie Schaaf, Senior Planner - PCPC

Jon Edelstein, Mngr.Brnfld Redev. - Dept of Comm. *

Mike Kates - Trolley Works

Donna Henry - Exc.Dir, S.W. Comm.Dev. Corp. *

Karen Cilurso - Sen.Reg.Planner, DVRPC *

Sarah Clark Stuart - City P&R, Bike Coalition

DesignTeam – Joe Sullivan, Ammann & Whitney

Ahcène Larbi - Ammann & Whitney

Melissa Dimitriou - Ammann & Whitney Ted Agoos - Agoos/Lovera Architects

SRDC – Joseph R. Syrnick

Lane Fike

Joe Sullivan opened the meeting discussing the parameters of the project. He noted that exisiting Railroad bridge drawings were reviewed. The preferred clearance of 35' was pursued, but the Coast Guard stated that it was very doubtful that approval could be obtained. Vane Brothers tug boats require 50' clearance. The number of bride openings was supplied by Phila. DoS [2007 - 100 times, 2008 - 92 times, 2009 - 59 times, 2010 - 54 times]. The Coast Guard said that since the tug boat was supplying fuel to a power plant that serviced hospitals, the request for a restriction would likely be rejected.

Sarah asked if a movable bridge had been considered so that lower elevation could be used. Joe Syrnick said that the cost, logistics and liability of operating a movable bridge were thought to be unreasonable for this bridge. Sarah asked that we pursue option with Department of Streets. Joe said he would ask and that others make contacts as well if desired. Debbie said she could ask Commerce to give an opinion.

Sarah asked if the bridge could be cantilevered off of the GFA Bridge. It was explained that the 50" clearance no longer allowed for supporting the pedestrian bridge between the GFA Piers. The superstructure was not designed to carry the dead & live loads of a pedestrian bridge supported off of the highway fascia beams.

^{*} Not Present

Sarah was concerned about ramp intrusion on the west bank. Joe indicated that the ramp length would be the minimum and the immediate plan is to follow railroad to 49th Street. Once a trail is established along the river, the trail could link with bridge directly.

It was noted that use of the railroad bridge for a trail has not been formerly requested from CSX. SRDC will consider options for resolving this issue.

Ted Agoos presented several renderings showing the many options considered to date, including the 35' Clearance options. There were detailed renderings of the Options 3 & 4 which were believed to represent the most viable alternatives.

The consensus of those present was that Option three (3) was probably the most attractive. Option 4 with the truss and cable-stayed structure seemed cluttered.

The Project Team will take a closer look at the trail approaches and likely make a recommendation for a structure utilizing the existing railroad bridge. They will also seek additional funding for preliminary design of a structure that utilizes the existing Railroad bridge.



September 29, 2010

Clarena Tolson Streets Commissioner 720 Municipal Services Building 1401 JFK Blvd. Philadelphia, PA 19107

Re: Schuylkill Crossing at Grays Ferry

Dear Commissioner Tolson,

The Schuylkill River Development Corporation (SRDC) is working on the concept of a Schuylkill River crossing in the vicinity of Grays Ferry to carry the Schuylkill trail over the river. The focus of this study is an adaptive re-use of an abandoned railroad swing bridge located just south of the Grays Ferry Avenue Bridge.

It would be advantageous to have the river crossing made at an elevation as close as possible to the existing swing bridge. However, at this elevation there is low vertical clearance over the river such that a moveable bridge would be needed to accommodate current navigation by commercial river traffic.

SRDC, and our concept development team, would like to explore with you the possibility of constructing a moveable bridge at this location. While SRDC would be responsible for securing the capital cost of this structure, we are not in a position to operate and maintain it. These tasks, we believe are something that would more appropriately fall to the City. We note that the City currently operates the 34th Street Bridge (aka University Avenue) which is just upstream from our proposed site.

Could we meet with you and your operations team to present our proposal and discuss how we might proceed? As you know the development of the Schuylkill trail is a high priority of the City Administration and this river crossing is a critical link which will connect the trail to Bartram's Garden.

If you could provide some dates and times for such a meeting, we should appreciate it.

Sincerely,

Joseph R. Syrnick President & CEO

cc: Kevin Koch



CITY OF PHILADELPHIA

STREETS DEPARTMENT 7th Floor - Municipal Services Building 1401 JFK Boulevard Philadelphia, Pennsylvania 19102-1676 CLARENA I. W. TOLSON Commissioner

November 9, 2010

Joseph R. Syrnick President and Chief Operating Officer Schuylkill River Banks 2929 Arch St. – 13TH Floor (Cira Center) Philadelphia, PA 19104-7391

RE: Swing Bridge over the Schuylkill River

Dear Mr. Syrnick:

Thank you for meeting with the Department of Streets to discuss your vision for the extension of the Schuylkill River Trail by utilizing an abandoned rail road swing bridge over the Schuylkill River. In your September 29, 2010 letter you suggested that the Schuylkill River Development Corporation (SRDC) would refurbish the swing bridge and that the City of Philadelphia Streets Department would operate and maintain it.

We support SRDC's mission and share its vision for a safe and convenient bicycle and pedestrian connection to Bartram's Gardens. In our service focus, the Streets Department does not have the resources to operate and maintain a swing bridge. The SRDC may need to seek another entity for these services or that you explore utilizing other crossings to connect Bartram's Gardens to the Schuylkill River Trail.

Good luck in your endeavors and thank you for all that you do.

Sincerely,

Clarena I.W. Tolson Streets Commissioner

c: Stephen Buckley, Deputy Commissioner of Transportation Branch David J. Perri, Surveys and Design

Sullivan, Joseph

From:

Lane Fike [lane.fike@srdc.net]

Sent:

Monday, January 24, 2011 9:21 AM

To: Cc: Joseph Syrnick Sullivan, Joseph

Subject:

comments

We recd comments from Louise, Sarah & Debby. None from Mike, Karen, Donna & Jon.

Louise had no comments. Debby asked for some changes but favors #3. Sarah wants lower bridge.

DoS was very adamant that they did not want a movable bridge.

I suggest we should incorporate Debby's comments in final report and send to all members. Indicate that we are moving forward with Option 3 Preliminary Design.

Lane B. Fike P.E.

Schuylkill River Development Corporation 2929 Arch Street 13th Floor Philadelphia PA 19104-7395 215-222-6030 ext.101



Sullivan, Joseph

From: Debby.Schaaf@phila.gov

Sent: Friday, January 21, 2011 5:16 PM

To: Lane Fike

Cc: Donna@southwestcdc.org; Edelstein Jon; Joseph Syrnick; Sullivan, Joseph; Cilurso, Karen

P.; Turan Louise; Kates Michael; sarah@bicyclecoalition.org

Subject: Re: Conceptual Report

Attachments: pic16512.gif

Lane,

Here are my comments on the report:

- Figure 1 should be more detailed in showing the existing bridge and existing and planned trail sections.
- Truss Concept 3 and Cable Concept 1 both should mention as advantages the fact that they would give prominence to an artifact that gives insight into the history of the river.
- The aesthetic comments on the alternative designs are subjective and should not be grouped with more factual statements. For example, I think that the "difference in truss span and depth" in Truss Concept 2 is more attractive than the "more consistent look" of Truss Concept 1.
- As I recall the stakeholder meeting in September, and according to the meeting notes in the Appendix, there was not a consensus second choice after Truss Concept 3. I was the person who made the comment about Option 4, Cable Stay Concept 1, being a bad mixture of old and new, and I don't remember hearing the arguments in favor of it. (I saw a lot of pictures of Option 5 and had the impression that was the favored option coming into the meeting.) I continue to think Option 4 is a poor option. If you look at the advantages and disadvantages of these two options, as laid out in the report, they are almost exactly the same. If re-using the existing truss proves workable, we should use Option 3. If it proves unworkable for whatever reason, then we should consider Option 5 or Option 6.

Deborah Schaaf Philadelphia City Planning Commission One Parkway Building, 13th floor Philadelphia PA 19102

Phone: 215-683-4643 Fax: 215-683-4630 debby.schaaf@phila.gov

"Lane Fike" <lane.fike@srdc.net>

"Lane Fike" <<u>lane.fike@srdc.net</u>>

12/23/2010 04:09 PM

To"Turan Louise" < lturan@bartramsgarden.org, "Kates Michael" < mkatesptw76@aol.com, < sarah@bicyclecoalition.org,

"Cilurso, Karen P." <kpcilurso@dvrpc.org>,

<Debby.Schaaf@phila.gov>, <Donna@southwestcdc.org>,

"Edelstein Jon" < jon.edelstein@phila.gov>

cc"Joseph Syrnick" <<u>joseph.syrnick@srdc.net</u>>, "Sullivan Joe" <<u>JSullivan@Ammann-Whitney.com</u>>

Dear Crossing Concept Committee Team Member...

Amman & Whitney has submitted the pre-final report for the feasibility study of a Schuylkill River Crossing at Grays Ferry. The report as presented has a draft recommendation on page 14.

We are seeking your comments prior to finalizing the report and we may need to do a bit more inspection of the existing truss to assure that it is re-usable.

We recognize that this is a busy time of year but could we get your comments by January 21, 2011?

We appreciate your work on this project and hope that you have a great holiday.

Lane B. Fike P.E.

Schuylkill River Development Corporation 2929 Arch Street 13th Floor Philadelphia PA 19104-7395 215-222-6030 ext.101

[attachment "Grays Ferry Ped Bridge Conceptual pdf Report to Stake Holders.pdf" deleted by Debby Schaaf/CityPlan/Phila]





Thursday, September 29, 2011

Joseph Syrnick Lane Fike SRDC

Dear Joe and Lane,

Thank you for the opportunity to comment on this report.

I appreciate participating as a stakeholder for this feasibility study and I did concur with the rest of the group on the design of the bridge section. However, I still do not agree that the bridge should be 50 feet high. I recommend that SRDC work with other partners (including the Bicycle Coalition and other trail advocates) to pursue finding a way to make it possible for a bridge to be constructed as close as possible to grade level or be built as a movable bridge to allow ship traffic as necessary, instead of being 50 feet high.

The height restriction is driving the designs for this bridge to be higher, with steeper slopes and probably more expensive than what is expected of this bike/ped crossing. Given that it is imperative that the trail cross the river over the western riverfront, finding a design that fits into the City's physical landscape and into the needs of the Schuylkill River Trail, we strongly recommend that alternatives be pursued. We recognize that maintenance is a barrier, but we are convinced that more could be done to determine if that barrier could be overcome.

Although Commissioner Tolson's letter states that the City doesn't have the resources to operate and maintain a moveable bridge, the letter did not reject it outright as a concept. She suggested seeking another entity for those services.

We have several ideas or questions about operating and maintaining a new movable bridge or re-activating the existing swing bridge.

• Is it possible to get a rough idea of the cost of operating and maintaining a movable bridge? (For example, how much does the City spend on the University Avenue Bridge?). If the amount is reasonable, isn't it conceivable that the funds to operate and maintain the bridge could be raised and that the operation and maintenance could be contracted out to a third party? Even if it has to be opened 30-50 times a year, couldn't someone be hired on a contractual basis for those several hours of 30-50 days? For that matter, couldn't a fund be created to pay for the cost of the additional work for the city employee who operates the University Avenue Bridge?





- Could a remote operation be explored? Conceivably, if and when the University Avenue Bridge has to be raised, couldn't the city's operator raise the Gray's Ferry Crossing remotely? I realize this requires additional safety measures to ensure that no one is on the bridge at the time it needs to go up, but couldn't that be handled with cameras and gates? Couldn't the cost of installing the equipment necessary to operate remotely be built into the capital costs of the construction?
- How frequently does the CSX RR bridge open south of the study area? Is it opened remotely or by an operator? Is it possible that CSX could be contracted with to open the bridge (either manually or remotely)?

The reasons we prefer a new movable bridge or reactivated swing bridge are as follows.

- 1) **Approaches to a 50 foot high bridge will be long, steep and high.** As proposed in the feasibility study, the approach to the bridge on the eastern bank of the bridge would begin at 36th Street (the FedEx driveway) and rise up to the 50 foot level. (According to Google Earth), the ramp would be approximately 880 feet to the eastern bank. On the western side, the ramp down from the bridge will curve to the south and run along the CSX tracks and could be approximately 1400 feet long.
- 2) A steep approach will mitigate green space access. These proposed ramps lengths and steep slopes will discourage people from making the effort to cross the River, especially short-distance bicyclists from southwest who wish to connect to Center City and the rest of the Schuylkill River Trail. Extending the Schuylkill River Trail to Southwest Philadelphia should be opening up green space to a population that currently doesn't enjoy that access. A 50 foot high bridge could potentially act as barrier to that access. I'm also concerned that the eastern approach will have such a steep slope that it will become a turnaround area as opposed to an invitation to cross the River.
- 3) Lower bridges are easier to navigate and more inviting. As mentioned above, we're concerned that a bridge with a steep grade will be an effective barrier to those who just don't feel they can manage the climb (whether on a bike or walking) or who have vertigo. A bridge closer to the water has a more intimate feel, a feeling of closeness to the riverbanks and that you are part of the River, as opposed to flying over it. What is appealing about a lower bridge that moves to accommodate river traffic is its proximity to the water and it's singularity of use.
- 4) **Proposed western approach would shoehorn industrial development closer to the River.** The proposed long ramp on the western side of the River is situated in CSX's right of way. What if PIDC was considering using this ROW to augment the National Heat and Power (NHP) property for its industrial development plans for its site? Presumably, if the ramp is placed on the CSX ROW and PIDC can no longer get access to it, the area available for industrial development would be smaller and force that development closer to the River. PIDC's Infill Project anticipated a bridge that is effectively atgrade with much lower and shorter approaches and a tie in directly into the riverfront path.





5) The space for a riverfront trail is being made available now. I have learned that PIDC and Dept. of Parks and Recreation are in the process of negotiating the transfer of 5 acres of land along the river to make it available for a riverfront trail. (It was announced on December 7th when Green2015 was launched and I learned at last night's Park and Rec. Commission meeting that Mark Focht is charged with moving forward on the transaction; so this is moving. I got the sense from the announcement made at the Park and Rec. Commission meeting that DPR is touting this transaction as the beginning of its effort to work towards the 500 acre goal.) It is our understanding that PIDC wants to keep the public as close to the river as possible to keep them separated from the industrial sections of the NHP site. The current ramp proposal doesn't anticipate the riverfront path; it is designed for the CSX ROW only. Given that the transaction is close at hand, and that DPR is going to make this 5 acres part of its Greenworks 500 acres of new park land goal, shouldn't the design of the bridge tie into the riverfront parcel now?


On behalf of the Bicycle Coalition, I recommend the following.

- SRDC continue to explore and cost out movable bridge technologies for a bike/ped bridge. (This link is
 intriguing <u>Bridge of Scottish Invention</u> (designed by <u>Bennett</u>)). We suggest inviting bridge engineers
 from several local firms to review the report and ask them for their ideas on options for a movable
 bridge that meets the criteria of minimal operation and maintenance costs. Perhaps Bennett could be
 asked to provide some kind of cost estimate.
- We strategize with you on meeting with Trigen and/or the tugboat company about the height issue.
- The Bicycle Coalition and other members of the Complete the Trail Coalition meet with the Streets Department and Mayor's Office of Transportation to discuss the moveable bridge concept.
- We would like to join you at a meeting with PIDC and the Parks and Recreation Department to discuss how the bridge will fit into their plans for the riverfront trail.

I look forward to further discussing our recommendations this with you.


Sincerely,

Sarah C. Stuart Campaign Director























Schuylkill River Trail Public Meeting

Home » Event

February 8, 2012 - 6:00pm - 8:00pm

Information on the trail

Location

Rainey Auditorium, Penn Museum, 3260 South Street Philadelphia, PA, 19104

Tags: <u>Bicycling Development & Sustainability University City University of Pennsylvania Coalition</u>

PlanPhilly.com is a project of PennPraxis, the clinical arm of the School of Design of University of Pennsylvania. **MORE**

APPENDIX G


(Inspection Report)



Schuylkill River Development Corporation

Conceptual Design Services for Grays Ferry Pedestrian Bridge, Philadelphia, PA Project No. GFP-1

Inspection Report



Grays Ferry Pedestrian Bridge over The Schuylkill River

PREPARED BY:



INSPECTION REPORT
Grays Ferry Pedestrian Bridge over Schuylkill River
Concept Design Services

TABLE OF CONTENTS


I.	LOCATION MAP	1
II.	AERIAL VIEW	7
11.		*********
III.	EXECUTIVE SUMMARY	3
IV.	EXISTING STRUCTURE INFORMATION	4
	1. Location & Surroundings:	2
	2. Superstructure:	
	3. SUBSTRUCTURE:	
	4. Mechanical:	
	IN-DEPTH INSPECTION FINDINGS	
V.		
	1. General:	5
	2. SWINGSPAN TRUSS:	
	3. Stringers:	7
	4. Floorbeams:	8
	5. BOTTOM CHORD CROSS BRACING:	8
	6. TOP CHORD CROSS BRACING:	
	7. PORTALS:	9
	8. MECHANICAL SYSTEM STRUCTURAL COMPONENTS:	
	9. Fender System:	10
	10. Abutments & Wingwalls:	
	11. Retaining Wall:	10
	12. Piers:	11

APPENDIX A: Figure 1: Truss Node Designations

Inspection Photographs **APPENDIX B:**


Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

I. Location Map



Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

II. Aerial View



Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

III. Executive Summary

The objective of the inspection and this report was to list all structural defects needed to evaluate applicable superstructure and substructure repairs.

An in-depth inspection was performed between June 21 and June 23, 2011 to assess the existing structural condition of the bridge. No existing inspection reports were available. The railroad and mechanical systems were not inspected as they will be removed during the rehabilitation.

Overall, the bridge was in fair to poor condition. The structural integrity of the superstructure has not been compromised; however, the extent of steel repairs needed to extend the life of the structure will be costly. The superstructure steel had many areas of severe deterioration below the deck rails, particularly in bottom chords, gusset plates, and lateral bracing. The substructure stone abutments and piers had minimal areas of concern. The concrete retaining wall at the north end of the East Approach had several areas of deteriorated and spalled concrete. The paint system has failed throughout the entire superstructure with moderate to severe surface rust typical.

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

IV. Existing Structure Information

1. <u>Location & Surroundings:</u>

The proposed pedestrian bridge is located adjacent to the existing Grays Ferry Avenue highway bridge over the Schuylkill River. The proposed bridge, which is in the location of the abandoned Conrail swing bridge, will serve as a key connection in the Schuylkill Banks trail. The Schuylkill Banks trail stretches between the Art Museum and Locust Street, and there are several sections under design south of Locust Street. The ultimate goal of the Schuylkill River Development Corporation (SRDC) is for the trail to continue down the east bank of the river to Grays Ferry and then cross over to the west bank to enable a connection to Historic Bartram's Garden and ultimately to Fort Mifflin.

2. Superstructure:

The existing structure, which was built in 1901, consists of four spans over the Schuylkill River. Each 97'-9 3/8" approach span is made-up of two 8'-6" deep steel plate girders. The existing 226'-3" long swing steel truss is currently supported in the open position at midspan with two equal cantilever spans. The bridge carried one non-electrified freight line. The truss is permanently in the open position since the structure and rail line were abandoned by its owners. It is assumed and very likely that the mechanical systems do not function anymore.

3. Substructure:

Both abutments and all three piers are constructed of stone masonry. The breastwall of the West Abutment and all three piers were in the water. The East Abutment was outside of the waterway along the river bank.

4. Mechanical:

The mechanical systems were not inspected as a part of this inspection. They will be removed during the rehabilitation. The girder supports below the truss bottom chord were inspected for structural defects only.

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

V. In-Depth Inspection Findings

1. General:

Ammann & Whitney, Inc. performed an in-depth inspection of the entire bridge structure between June 21 and June 23, 2011 to assess the existing condition of the bridge (Photos 1.1 to 1.5). The inspection of the West Abutment, piers, and truss utilized a bucket boat from above the waterline.

The field inspection consisted of a hands-on examination of the bridge to determine the extent of structural deterioration. Field notes, sketches, and photographs were used to record all observations. A Structural Inventory and Appraisal (SI&A) value was assigned to each element of the bridge to designate the degree of deterioration. It is noted that the inspection did not cover every single defect but enough to have a good representation of the general condition of the structure.

Note that the abutments and piers were numbered from west to east. The truss elements were numbered from the north (upstream) and south (downstream). See Figure 1 for truss node designations. The truss was in the open position during the inspection.

2. Swingspan Truss:

Overall, the swingspan was in fair to poor condition (SI&A 5/4).

a. General Notes:

- Overall, the paint system had failed with no paint remaining. The entire structure, at minimum, had surface rust and minor pitting.
- The areas with the most corrosion were located at node points, particularly at the gusset plates in the bottom chord.
- Any horizontal flat area below the bottom chord had some degree of delaminated rust buildup.
- Minor to moderate pack rust between flange plates was typical at the bottom chord field splices.
- Minor to 100% section loss in the chord lacing bars at the connection to the chord channels (Photos L.1 to L.3). Pack rust has caused numerous lacing bars to bow (Photo L.4).

b. Truss Bottom Chords:

- Bottom Chord Members:
 - o (L0-L1)_{W US}: Moderate delaminated rust of top flanges at node L1_{W US} (Photo BC.1).
 - o $(L4-L3B)_{W_US}$: Bottom tie-plate broken in half due to deterioration immediately north of gusset plate at node $L4_{W_US}$ (Photos BC.2 & BC.3). The tie-plate north of the broken plate was also severely deteriorated. Both bottom flanges of the channels were severely knife edged up to 3'-6" north from node $L4_{W_US}$.
 - o (L3B-L3) $_{W_{LUS}}$: Top flange tie-plate had 100% section loss and severe delamination throughout adjacent to L3 $_{NW}$ (Photo BC.4).
 - o (L3B-L3) $_{W_US}$: Bottom flange severe pitting with section loss 1'-0" long from edge of gusset at node L3 $_{W_US}$.
 - o (L3-L3B)_{W_DS}: 2'-5" long x 5" high hole in the east channel web above the gusset plate at the south side of L3B_{W_DS} (Photo BC.5). The bottom flange had severe deterioration and section loss at the same location (Photo BC.6). 4" wide x full height severe deterioration

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

- in the east channel web immediately adjacent to the south side of L3_{BSW DS}.
- o (L3-L3B) $_{W_DS}$: Heavy pitting 1½" wide x 1'-3" high (full height) with a 1½" wide x 3" high hole in the west channel web immediately south of the gusset plate at node L3B $_{SW_DS}$ (Photo BC.7).
- o (L3-L3B)_{W_DS}: Three (3) broken lacing bars due to corrosion immediately south of the gusset plate a node L3B_{W_DS} (Photo BC.8).
- (L3-L4)_{W_DS}: Bottom tie-plate severe deterioration immediately south of node L4_{SW} (Photo BC.9). Seven (7) bottom flange lattice bars broken, necked down, or bent at same location.
- o $(L3-L4)_{W_DS}$: Top tie-plate severe deterioration and warping due to pack rust immediately south of node L3B_{SW}. Same condition for tie-plate north of node L4_{W DS}.
- o (L3-L4)_{E DS}: 9" x 9" hole in west channel web at L3_{E DS} (Photo BC.10).
- o (L3-L4)_{E_DS}: 2'-0" long x 8" high hole in the west channel web above the gusset plate at the south side of L3B_{E_DS} (Photos BC.11 & BC.12). The following bullet below describes similar holes at the same node point.
- o (L3-L4)_{E_DS}: 2'-0" long x 6" high hole in the west channel web above the gusset plate at the north side of L3B_{E_DS} (Photo BC.13). There was also a 2"x2" hole in the web 2'-0" north of the hole at the gusset (Photo BC.14). The 2'-0" length between holes had heavy pitting on the inside on the back face of the web.

• Bottom Chord Splice Plates:

- o (L0-L1)_{W US}: Splice plates at L1_{W US} bowed along outside edge due to ¹/₄" pack rust.
- o (L2-L3) $_{W_US}$: Splice plates at L3 $_{W_US}$ bowed along outside edge due to ½" pack rust (Photo SP.1).
- o $(L2-L3)_{W_DS}$: Splice plates at $L3_{W_DS}$ bowed along outside edge due to ½" pack rust. Top plate had a popped rivet head due to the stress created by the pack rust (Photo SP.2).
- o (L0-L1)_{E_DS}: Splice plates at L1_{E_DS} bowed along the outside edges due to $\frac{3}{4}$ " max pack rust (Photo SP.3).

• Bottom Chord Gusset Plates:

- Gusset plates and corresponding cross bracing were generally in worse condition in areas with timber planking walkways spanning between floorbeams. The planks held moisture against the gussets (Photo GP.1).
- o $L0_{W_{LUS}}$: Delaminated rust, including ten (10) rivets, along the bottom 6" height of the east vertical gusset plate connecting the bottom and diagonal chords (Photo GP.2).
- L1_{W_US}: Large accumulation of delaminated rust atop the gusset plate at southeast corner adjacent to crossbrace (Photo GP.3). Typical in several locations.
- o L2_{W_US}: Large accumulation of delaminated rust atop gusset plate at southeast and northeast corners adjacent to crossbraces (Photo GP.4).
- o L3 $_{W_US}$: 100% section loss 1'-6" wide x 4" long on the south edge and 1'-0" long x 4" wide on the southeast edge (Photo GP.5).
- o L3B_{W_US}: Severe delaminated rust with 100% section loss 1'-0" long x full width of bottom chord at the north and south edges (Photo GP.6).
- o L4_w: Severe pitting and corroded rivets throughout plate (Photo GP.7). Two 3"x3" holes at the top of the plate. Timbers were resting at the location of the holes indicating trapped moisture led to the deterioration.

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

- L2_{W_DS}: Popped rivet due to 1" thick pack rust between gusset plate and bottom chord (Photo GP.8)
- o L3B_{W_DS}: Severe delaminated rust at south end 1'-0" long x 2'-0" wide. 7" long x 9" wide hole at the edge of the gusset adjacent to the chord (Photo GP.9).
- o L3B_{E US}: 6"x6" hole at the south end of the gusset below the chord (Photo GP.10).
- o L3B_{E_US}: 2'-0" long x 1'-2" wide severe delaminated rust with section loss below the chord at the north end of the gusset. 3" long x 9" wide area at north end below a wooden timber support. 6"x6" delaminated area at northwest corner; slightly bent due to $\frac{1}{2}$ " pack rust (Photo GP.11).
- L4_E: Several holes through the vertical gusset plate (Photo GP.12 & GP.13).
 - From north to south:
 - 1¼" wide x 1'-6" high, 1'-9" from the bottom
 - 8" wide x 10" high, 1'-4" from the bottom
 - 5" wide x 8" high, 1'-9" from the bottom
 - 8" wide x 9" high, 1'-7" from the bottom
 - 1¼" wide x 1'-9" high, 1'-7" from the bottom.
 - Severe accumulation of delaminated rust behind the gusset plate.
- o L1_{E_DS}: Delaminated rust at north end 1'-0" long x 2'-6" wide (full width). Included within this area was a 4" long x 9" wide and 2" long x 6" wide severely delaminated area up to 100% section loss (Photo GP.14). The south end had a 6" long x 4" wide hole adjacent to the chord and a 1'-0" x 1'-0" area of 35% section loss below the chord.
- o L2_{E_DS}: Severe delaminated rust at north end 1'-0" long x 2'-6" wide (full width).
- o L3_{E_DS}: Severe delaminated rust with section loss at north end 1'-0" long x 1'-0" wide (Photo GP.15). Also see Photo GP.12 above.

c. Truss Verticals

- o (L3-U3)_{E US}: ½" pack rust between top of gusset and east vertical channel at node L3_{E US}.
- o (LM-MC)_{W_DS}: 3" high x full width hole in the south flange of the west channel at the base of the vertical at LM_{W_DS} (Photo V1.1). Bottom two (2) lacing bars 100% section loss and five (5) lacing bars with severe section loss.

d. Truss Diagonals

- o (L0-U1)_{W US}: Six (6) missing rivets where bridge name plate was attached to chord.
- o $(L4-U3)_{W_US}$ & $(L4-U3)_{W_DS}$: 1'-4" knife edging along the horizontal leg of the top flange angle for both diagonals at L4 (See Photo GP.7).

3. **Stringers:**

The stringers were in fair condition (SI&A 5).

- o Typical: Large accumulation of delaminated rust along the entire length of the top face of the bottom flanges (Photo S.1).
- o Typical: Rivets delaminated along bottom flange angles.
- Typical: Severe 1" thick pack rust between stringer bottom flange and seat angle at stringer-to-floorbeam connection. This detail may have been for construction purposes only (Photo S.2).
- o Typical: Top flange cover plate knife edged between timber rail ties (Photo S.3).

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

- o $S1_{N_{LIS}}$: 1" diameter hole in web 1'-0" from bottom flange and 9" away from Floorbeam $F0_{N_{LIS}}$.
- o S1_{N_US}: 5'-0" long severe delaminated rust accumulation along top of bottom flange due to moveable bridge components spanning between stringers (Photo S.4).
- o S1_{S DS}: 1'-6" long x 3½" high hole at base of web above bottom flange angle (Photo S.5).
- S1_{S_DS}: 10'-0" long severe knife edging resulting in 100% section loss along the east edge
 of bottom flange cover plate near midspan (Photos S.6 & S.7). Seventeen (17) rivets had
 excessive deterioration.
- o S1_{S_DS} & S2_{S_DS}: Severe pack rust accumulation atop bottom flange due to truss dead weight storage spanning between stringers (Photos S.8 & S.9).

4. Floorbeams:

The floorbeams were in satisfactory condition (SI&A 6).

- o Typical delaminated rust accumulation along the top face of the bottom flanges.
- o FO_{S DS}: One missing rivet in bottom flange angle adjacent to west stiffener (Photo FB.1).

5. Bottom Chord Cross Bracing:

The bottom chord cross bracing was in serious condition (SI&A 3).

- L1_{US}: Two (2) failed riveted connection at crossbrace-to-stringer support angle. One at each of S1_{US} and S2_{US} stringers. One (1) rivet through vertical leg deteriorated at midspan.
- o (L2-L3)_{US}: The splice plate at the intersection with L1_{US} was bowed due to severe pack rust.
- o L2_{US}: Failed riveted connection at crossbrace-to-stringer support angle.
- o L4_{1_US}: Failed riveted connection at crossbrace-to-stringer support angle (Photo BX.1). Also, two (2) deteriorated rivets in horizontal leg to splice plate.
- o L4_{1_US}: 3'-0" long x full width of west angle severe delaminated rust with section loss adjacent to gusset plate at node L2_{W US} (Photo BX.2).
- o (L5-L6)_{1_US}: The splice plate at the intersection with L4_{1_US} had severe pitting on both sides of L4_{1_US}. There were also four (4) deteriorated rivets in the horizontal leg of L6_{1_US} at the splice.
- o L4_{2 US}: Failed riveted connection at crossbrace-to-stringer support angle.
- o L4_{2 US}: Severe delaminated rust 1'-0" long at node L3_{NW US}.
- o L5_{2_US}: Severe delaminated rust up to 100% section loss in horizontal leg 2'-0" from node L2_{W_US}.
- o $L7_{N_LUS}$: Field welded repair to fix deteriorated rivet heads 5'-0" from gusset at node $L3B_{W\ US}$ (Photo BX.3).
- o L6_{1 US}: Failed riveted connection at crossbrace-to-stringer support angle (Photo BX.4).
- o $L6_{1_US}$: 3'-0" long x full width of bottom flange severe delaminated rust with section loss adjacent to gusset plate at node $L1_{W\ US}$ (Photo BX.5).
- o $L6_{2_US}$: 3'-0" long x 5" wide severe delaminated rust on west angle of brace at node $L2_{W\ US}$ (Photo BX.6).
- o L1_{DS}: 1'-0" long x 3" wide severe knife edging and pitting in both legs of brace (Photos BX.7 & BX.8).

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

- o L2_{DS}: 10" long x 3" wide section loss up to 100% in horizontal leg of brace (Photo BX.9).
- o L2_{DS}: 1'-0" long x 3" wide section loss up to 100% in horizontal leg of brace at both sides of splice (Photo BX.10).
- o (L2-L3)_{DS}: 2'-0" long severe section loss resulting in 1/8" remaining section in horizontal leg in the splice plate between L2_{DS} and L3_{DS} (Photo BX.11).
- L6_{2_DS}: Several small holes in horizontal legs within a 1'-0" length x 10" width (full width) approximately 4'-0" from node L3B_{W_DS} (Photo BX.12). Severe pitting and five (5) popped rivet heads in the vertical leg at the same location (Photo BX.13).
- o L8_{DS}: 6" long x $1\frac{1}{2}$ " wide $\frac{1}{4}$ " section loss 1'-8" from the intersection with L7_{DS}.

6. Top Chord Cross Bracing:

The top chord cross bracing were in poor condition (SI&A 4).

- o The top chord cross bracing consists of back-to-back angles for top and bottom flanges with a lattice bar web (Photos TX.1 & TX.2).
- O Typical: Numerous areas of moderate to severe necking of the lattice bars at intersection with back-to-back flange angles (Photos TX.3 & TX.4).
- o $T2_1$ - $T3_1$: Top flange splice plate and bottom flange angles bowed at cross brace intersection due to pack rust between truss nodes U_1 and U_2 (Photos TX.5).
- o T2₂-T3₂: Top flange splice bowed at cross brace intersection due to pack rust between truss nodes U₂ and U₃.

7. Portals:

The portals were in good condition (SI&A 7).

- No significant defects noted (Photos PT.1 through PT.4).
- o Moderate to severe pack rust between bottom chord back-to-back angles was typical (Photos PT.5 & PT.6). The angles are bent in these locations (Photo PT.6).

8. Mechanical System Structural Components:

The mechanical system structural steel was in poor condition (SI&A 4).

- Several photos document how the mechanical system is connected to the truss (Photos ME.1 to ME.9).
- Several large holes in the brace plate between CG_{DS} and CG_{US} on the east side (Photo ME.2).
- CG_{US}: Majority of rivets on the north face, east side of bottom flange are deteriorated (Photo ME.10). Upto 4" of delaminated rust accumulation on bottom flange.
- Both stringers between PG and CG_{DS} have upto 100% section loss 1'-2" long x full width
 of bottom flange angle at CG_{DS} connection (Photo ME.11). Nine rivets on the west
 stringer have severe section loss.

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

9. Fender System:

The timber fender was in a failed condition (SI&A 0).

- o The majority of the timber piles and whalers have decayed passed their useful life. Several areas of the fender system are completely missing particularly adjacent to the east and west sides of the center pier. See photos throughout other sections.
- o The center pier and truss (in the open position) are not adequately protected against ship traffic.

10. Abutments & Wingwalls:

The abutments were in good condition (SI&A 7).

a. General Notes:

- The abutments and wingwalls will be reused as retaining walls for the new reinforced concrete abutments to be constructed behind them.
- No cracked or fractured noted.
- Mortar typically cracked and/or missing.
- The bottom two to three courses have missing mortar throughout. This can be attributed to the portion of the pier in the tidal zone.
- Minor efflorescence present at the mortar joints.
- Rust and grease staining present on faces below the superstructure.

b. West Abutment:

- General Notes typical (Photos WA.1 to WA.4).
- No misaligned or shifted stones noted.
- The footing was not visible from the waterline.

c. East Abutment:

- General Notes typical (Photos EA.1 to EA.4).
- The capstone at the fascia of each cheekwall has shifted due to vegetation growth in the joints. The integrity of the capstone has not been compromised.

11. Retaining Wall:

The retaining wall was in satisfactory condition (SI&A 6). (Photos RW.1 to RW.3)

a. General Notes:

- o There were several areas of deteriorated concrete along the top cap.
 - 2'-0" long x 6" high spall at 98'-0" from the west end of the wall
 - 5'-0" long x 6" high spall at 182'
 - 9'-0" long x full height spall at 210'
 - 21'-0" long x full height spall at 219'
 - 30'-0" length x full height x full width severely spalled at 270'
- o Spalled and delaminated concrete typically located at the vertical construction joints
 - 6" long x 4'-0" high at located 180' from the west end of the wall
 - 3'-0" wide x 4'-6" high at 210'

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

- 6" long x 2'-0" high at 240' (Photo RW.5)
- 2'-6" long x 2'-6" long at 270'
- The top cap has minor horizontal hairline cracks with efflorescence typically throughout. (RW.4)
- o 15'-0" length of heavy efflorescence at 55' from the west end of the wall
- o 30'-0" length of moderate efflorescence between the joints located 240' and 270' from the west end of the wall (Photo RW.6).
 - 2'-0" long x 6" high spall at 314'
 - 2'-0" long x 6" high spall at 329'
- o The deteriorated two strand steel railing atop the wall should be removed.
- o Dense vegetation growth was obstructing portions of the wall.
- o It appears the wall may be unreinforced due to the depth of the spalls beyond the typical location for reinforcement behind cover.

12. Piers:

The stone masonry piers were in good condition (SI&A 7).

a. General Notes:

- No cracked or fractured stones.
- Mortar typically cracked and/or missing.
- The bottom two to three courses have missing mortar throughout. This can be attributed to the portion of the pier in the tidal zone.
- Minor efflorescence present at the mortar joints.
- Rust and grease staining present on faces below the superstructure.

b. West Pier:

- General Notes typical (Photos WP.1 to WP.6).
- No misaligned or shifted stones noted.

c. Center Pier:

- General Notes typical (Photos CP.1 to CP.3).
- No misaligned or shifted stones noted.
- The mechanical systems for the swing bridge are connected to the top of the pier.

d. East Pier:

• General Notes typical (Photos EP.1 to EP.4).

Pedestal


O Two of the stones below the south wedge bearing shifted to the east 1" (Photo EP.5). Vegetation was present in the joints.

• Capstone


The two triangular end capstones shifted slightly due to vegetation growth in the joint (Photo EP.6).


INSPECTION REPORT APPENDIX A

Figure 1: Truss Node Designations



TOP CHORD PLAN





BOTTOM CHORD PLAN

LEGEND:

US - DENOTES UPSTREAM
DS - DENOTES DOWNSTREAM

SCHUYLKILL RIVER DEVELOPMENT CORPORATION

PHILADELPHIA COUNTY
GRAYS FERRY AVENUE PEDESTRIAN TRAIL
FIGURE 1

H: \PA-CLIENTS\3061\3061-Reports\Inspect

DWG. NAME: Framing_Plan.dgn

INSPECTION REPORT APPENDIX B

Inspection Photographs

INSPECTION REPORT

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

GENERAL



PHOTO 1.1: East Elevation looking northwest.



File: DSC05176.JPG



PHOTO 1.2: West Elevation looking southeast.



File: img_1474.JPG



PHOTO 1.3: General view looking southwest.



File: img_1477.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

GENERAL




PHOTO 1.4: Looking south through truss.

1.4

File: DSC05111.JPG




PHOTO 1.5: General view of West Abutment and West Pier looking southwest.

1.5

File: DSC05144.JPG

TRUSS MEMBER LACING



PHOTO L.1: Typical severe necking adajcent to connection.



File: DSC05025.JPG



PHOTO L.2: Worst case deterioration leading to 100% section loss.



File: DSC05035.JPG



PHOTO L.3: Typical view of lacing bar with 100% section loss.




File: DSC05101.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

TRUSS MEMBER LACING





File: DSC05019.JPG

Truss Bottom Chords



PHOTO BC.1: $(L0-L1)_{W_{US}}$: Moderate delaminated rust of top flanges at node L1_{W_US}.

BC.1

File: DSC05151.JPG



PHOTO BC.2: (L4-L3B)_{W_US}: Bottom tie-plate broken in half due to deterioration immediately north of gusset plate at node L4_{W US}.

BC.2

File: DSC05133.JPG



PHOTO BC.3: Same location at bottom chord shown in Photo BC.2.

BC.3

File: DSC05134.JPG

Truss Bottom Chords



PHOTO BC.4: $(L3N-L3)_{W_US}$: Top flange tie-plate had 100% section loss and severe delamination throughout adjacent to $L3_{W_US}$.



File: DSC05140.JPG



PHOTO BC.5: $(L3-L4)_{W_DS}$: 2'-5" long x 5" high hole in the east channel web above the gusset plate at the south side of L3B_{W DS}.



File: DSC05102.JPG



PHOTO BC.6: (L3-L4)_{W_DS}: The bottom flange had severe deterioration and section loss at the same location as shown in Photo BC.5.



File: DSC05103.JPG

Truss Bottom Chords



PHOTO BC.7: (L3-L4)_{W_DS}: Heavy pitting 1½" wide x 1'-3" high (full height) with a 1½" wide x 3" high hole in the west channel web immediately south of the gusset plate at node L3B_{W_DS}.

BC.7

File: DSC05106.JPG



PHOTO BC.8: $(L3-L4)_{W_DS}$: Three (3) broken lacing bars due to corrosion immediately south of the gusset plate a node $L3B_{W_DS}$.

BC.8

File: DSC05101.JPG



PHOTO BC.9: (L3-L4)_{W_DS}: Bottom tie-plate severe deterioration immediately south of node L4_{W_DS}.

BC.9

File: DSC05136.JPG

Truss Bottom Chords



PHOTO BC.10: $(L3-L4)_{E_DS}$: 9" x 9" hole in west channel web at $L3_{E_DS}$.

BC.10

File: DSC05058.JPG



PHOTO BC.11: $(L3-L4)_{E_DS}$: 2'-0" long x 8" high hole in the west channel web above the gusset plate at the south side of L3B_{E_DS}.

BC.11

File: DSC05059.JPG



PHOTO BC.12: Wider view of same defect shown in Photo BC.11.

BC.12

File: DSC05060.JPG

Truss Bottom Chords



PHOTO BC.13: $(L3-L4)_{E_DS}$: 2'-0" long x 6" high hole in the west channel web above the gusset plate at the north side of L3B_{E_DS}.

BC.13

File: DSC05061.JPG



PHOTO BC.14: (L3-L4)_{E_DS}: 2"x2" hole in the web 2'-0" north of the hole at the gusset shown in Photo BC.13.

BC.14

File: DSC05062.JPG

Truss Bottom Chord Splices



PHOTO SP.1: (L2-L3)_{W_US}: Splice plates at L3_{W_US} bowed along outside edge due to ½" pack rust.



File: DSC05141.JPG



PHOTO SP.2: (L2-L3)_{W_DS}: Splice plates at L3_{W_DS} bowed along outside edge due to ½" pack rust. Top plate had a popped rivet head due to the stress created by the pack rust.



File: DSC05099.JPG



PHOTO SP.3: $(L0-L1)_{E_DS}$: Splice plates at $L1_{E_DS}$ bowed along the outside edges due to $\frac{3}{4}$ " max pack rust.

SP.3

File: DSC05017.JPG

Truss Verticals



PHOTO 1.1: (LM-MC)_{SW_DS}: 3" high x full width hole in the south flange of the west channel at the base of the vertical at LM_{SW}.

V1.1

File: DSC05107.JPG

Truss Bottom Chord Gusset Plates



PHOTO GPC.1: Typical: Planks held moisture against the gussets.



File: DSC05043.JPG



PHOTO GP.2: $L0_{W_{US}}$: Delaminated rust, including ten (10) rivets, along the bottom 6" height of the east vertical gusset plate connecting the bottom and diagonal chords.



File: DSC05153.JPG



PHOTO GP.3: L1_{W_US}: Large accumulation of delaminated rust atop the gusset plate at southeast corner adjacent to crossbrace.



File: DSC05152.JPG

Truss Bottom Chord Gusset Plates



PHOTO GP.4: L2_{W_US}: Large accumulation of delaminated rust atop gusset plate at southeast and northeast corners adjacent to crossbrace.



File: DSC05123.JPG



PHOTO GP.5: L3_{W_US}: 100% section loss 1'-6" wide x 4" long on the south edge and 1'-0" long x 4" wide on the southeast edge.



File: DSC05139.JPG



PHOTO GP.6: L3B_{W_US}: Severe delaminated rust with 100% section loss 1'-0" long x full width of bottom chord at the north and south edges.



File: DSC05135.JPG

Truss Bottom Chord Gusset Plates



PHOTO GP.7: L4_W: Severe pitting and corroded rivets throughout plate. Two 3"x3" holes at the top of the plate. Timbers were resting at the location of the holes indicating trapped moisture led to the deterioration.



File: DSC05132.JPG



PHOTO GP.8: L2_{W_DS}: Popped rivet due to 1" thick pack rust between gusset plate and bottom chord.



File: DSC05100.JPG



PHOTO GP.9: L3B_{W_DS}: Severe delaminated rust at south end 1'-0" long x 2'-0" wide. 7" long x 9" wide hole at the edge of the gusset adjacent to the chord.



File: DSC05103.JPG

Truss Bottom Chord Gusset Plates



PHOTO GP.10: L3B_{E_US}: 6"x6" hole at the south end of the gusset below the chord.



File: DSC05084.JPG



PHOTO GP.11: L3B_{E_US}: 2'-0" long x 1'-2" wide severe delaminated rust with section loss below the chord at the north end of the gusset. 3" long x 9" wide area at north end below a wooden timber support. 6"x6" delaminated area at northwest corner; slightly bent due to ½" pack rust.

GP.11

File: DSC05116.JPG



PHOTO GP.12: L4_E: Several holes through the vertical gusset plate.

GP.12

File: DSC05129.JPG

Truss Bottom Chord Gusset Plates



PHOTO GP.13: Closeup of defect in Photo GP.12.



File: DSC05075.JPG



PHOTO GP.14: L1_{E_DS}: Delaminated rust at north end 1'-0" long x 2'-6" wide (full width). Included within this area was a 4" long x 9" wide and 2" long x 6" wide severely delaminated area upto 100% section loss.



File: DSC05049.JPG



PHOTO GP.15: L3_{E_DS}: Severe delaminated rust with section loss at north end 1'-0" long x 1'-0" wide.



File: DSC05057.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

Truss Stringers



PHOTO S.1: Typical: Large accumulation of delaminated rust along the entire length of the top face of the bottom flanges.

S.1

File: DSC05053.JPG



PHOTO S.2: Typical: Severe 1" thick pack rust between stringer bottom flange and seat angle at stringer-to-floorbeam connection. This detail may have been for construction purposes only.

S.2

File: DSC05044.JPG



PHOTO S.3: Typical: Top flange cover plate knife edged between timber rail ties.

S.3

File: DSC05051.JPG

Truss Stringers



PHOTO S.4: S1_{N_US}: 5'-0" long severe delaminated rust accumulation along top of bottom flange due to moveable bridge complonents spanning between stringers.



File: DSC05154.JPG



PHOTO S.5: S1_{S_DS}: 1'-6" long x 3½" high hole at base of web above bottom flange angle.



File: DSC05088.JPG



PHOTO S.6: S1_{S_DS}: 10'-0" long severe knife edging resulting in 100% section loss along the east edge of bottom flange cover plate near midspan.



File: DSC05094.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

PHOTOGRAPHS

Truss Stringers



PHOTO S.7: Same defect as noted in Photo S.6.



File: DSC05095.JPG



PHOTO S.8: S1_{S_DS} & S2_{S_DS}: Severe pack rust accumulation atop bottom flange due to truss dead weight storage spanning between stringers.



File: DSC05047.JPG



PHOTO S.9: Same defect and location as noted in Photo S.8. S2_{S_DS} Shown.



File: DSC05093.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

Truss Floorbeam



PHOTO FB.1: F0_{DS}: One missing rivet in bottom flange angle adjacent to west stiffener.

FB.1

File: DSC05086.JPG

Truss Bottom Chord Crossbraces



PHOTO BX.1: L4_{1_US}: Failed riveted connection at crossbrace-to-stringer support angle.



File: DSC05127.JPG



PHOTO BX.2: L4_{1_US}: 3'-0" long x full width of west angle severe delaminated rust with section loss adjacent to gusset plate at node L2_{W_US}.



File: DSC05145.JPG



PHOTO BX.3: L7_{US}: Field welded repair to fix deteriorated rivet heads 5'-0" from gusset at node L3B_{W_US}.



File: DSC05126.JPG

Truss Bottom Chord Crossbraces



PHOTO BX.4: L6_{1_US}: Failed riveted connection at crossbrace-to-stringer support angle.



File: DSC05147.JPG



PHOTO BX.5: L6_{1_US}: 3'-0" long x full width of bottom flange severe delaminated rust with section loss adjacent to gusset plate at node L1_{W_US}.



File: DSC05148.JPG



PHOTO BX.6: $L6_{2_US}$: 3'-0" long x 5" wide severe delaminated rust on west angle of brace at node $L2_{W_US}$.



File: DSC05143.JPG

Truss Bottom Chord Crossbraces



PHOTO BX.7: L1_{DS}, L2_{DS}, L3_{DS}: Defects in crossbracing and Stringer S1S. See Photos BX.8 through BX.11 for closer views.



File: DSC05092.JPG



PHOTO BX.8: L1_{DS}: 1'-0" long x 3" wide severe knife edging and pitting in both legs of brace.



File: DSC05092.JPG



PHOTO BX.9: L2_{DS}: 10" long x 3" wide section loss up to 100% in horizontal leg of brace.



File: DSC05089.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

PHOTOGRAPHS

Truss Bottom Chord Crossbraces



PHOTO BX.10: L2_{DS}: 1'-0" long x 3" wide section loss up to 100% in horizontal leg of brace at both sides of splice. Also see Photo BX.8. Also see Photo BX.8.

BX.10

File: DSC05090.JPG



PHOTO BX.11: (L2-L3)_{DS}: 2'-0" long severe section loss resulting in 1/8" remaining section in horizontal leg in the splice plate between L2_{DS} and L3_{DS}. Also see Photo BX.8.

BX.11

File: DSC05091.JPG



PHOTO BX.12: L6_{2_DS}: Several small holes in horizontal legs within a 1'-0" length x 10" width (full width) approximately 4'-0" from node L3B_{W_DS}.

BX.12

File: DSC05104.JPG

Truss Bottom Chord Crossbraces



PHOTO BX.13: L6_{2_DS}: Severe pitting and five (5) popped rivet heads in the vertical leg at the same location as defect in Photo BX.12.

BX.13

File: DSC05105.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

Truss Top Chord Crossbraces




PHOTO TX.1: The top chord cross bracing consists of back-to-back angles for top and bottom flanges with a lattice bar web. Looking south at south end of truss.

TX.1

File: DSC05026.JPG



PHOTO TX.2: Looking north from same location as Photo TX.1.



File: DSC05032.JPG



PHOTO TX.3: Typical: numerous areas of moderate to severe necking of the lattice bars at intersection with back-to-back angles. See Photo TX.4 for a closer view.



File: DSC0538.JPG

Truss Top Chord Crossbraces



PHOTO TX.4: Typical: numerous areas of moderate to severe necking of the lattice bars at intersection with back-to-back flange angles.



File: DSC05028.JPG



PHOTO TX.5: T2₁-T3₁: Top flange splice plate and bottom flange angles bowed at cross brace intersection due to pack rust between truss nodes U₁ and U₂.



File: DSC05034.JPG

Truss Portals



PHOTO PT.1: Typical view of portal at node U_{1_DS} .



File: DSC05036.JPG



PHOTO PT.2: Typical view of portal between U_{3_US} and $U3B_{US}$.



File: DSC05038.JPG



PHOTO PT.3: Typical view of portal at node U_{3_US} .




File: DSC5112.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

Truss Portals







File: DSC05110.JPG



PHOTO PT.5: Typical: Moderate to severe pack rust between bottom chord back-to-back angles. See Photo PT.6 for closer view.



File: DSC05071.JPG




PHOTO PT.6: Closer view of defect noted in PT.5. Note the angles are bent due to the pack rust.



File: DSC05070.JPG

MECHANICAL



PHOTO ME.1: Looking southwest at the mechanical system at the center pier.

ME.1

File: DSC05129.JPG



PHOTO ME.2: 100% section loss in the brace between the center girders. Closeup view of defect shown in Photo ME.1.

ME.2

File: DSC05075.JPG



PHOTO ME.3: General view looking north at Girder CG_{DS} .

ME.3

File: DSC05052.JPG

MECHANICAL



PHOTO ME.4: General view looking southwest at Girder CG_{US}.



File: DSC05080.JPG



PHOTO ME.5: General view looking north at Girder WG



File: DSC05067.JPG



PHOTO ME.6: General view of wheel bearing.



File: DSC05082.JPG

MECHANICAL



PHOTO ME.7: General view of gear between both center girders (CG).



File: DSC05056.JPG




PHOTO ME.8: General view of wedge motor cantilevered from west side of bridge near the center pier.



File: DSC05114.JPG



PHOTO ME.9: General view of wedge bearing at end of truss.



File: DSC05014.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

MECHANICAL







PHOTO ME.10: CG_{US}: Majority of rivets on the north face, east side of bottom flange are deteriorated.

ME.10

File: DSC05078.JPG

PHOTO ME.11: Both stringers between PG and CG_{DS} have upto 100% section loss 1'-2" long x full width of bottom flange angle at CG_{DS} connection

ME.11

File: DSC05064.JPG

WEST ABUTMENT




PHOTO WA.1: East Elevation looking northwest.



File: DSC05165.JPG



PHOTO WA.2: West Elevation looking southeast.



File: DSC05168.JPG



PHOTO WA.3: General view looking southwest.



File: DSC05170.JPG

INSPECTION REPORT Grays Ferry Pedestrian Bridge over Schuylkill River

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

WEST ABUTMENT



PHOTO WA.4: Looking south through truss.

WA.4

File: DSC05169.JPG

INSPECTION REPORT

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

EAST ABUTMENT



PHOTO EA.1: Looking east at the East Abutment. The East Pier is in the foreground.



File: DSC05073.JPG



PHOTO EA.2: Schuylkill Banks Trail adjacent to the East Abutment.



File: DSC05013.JPG



PHOTO EA.3: General view of south cheekwall. See Photo EA.4 for close-up view.



File: DSC05007.JPG

EAST ABUTMENT



PHOTO EA.4: Close-up view of capstone on south cheekwall. The capstone has shifted due vegetation in the joint.

EA.4

File: DSC05006.JPG

INSPECTION REPORT Grays Ferry Pedestrian Bridge over Schuylkill River **Concept Design Services**

PHOTOGRAPHS

RETAINING WALL



PHOTO RW.1: Looking east along path at midlength of wall.



File: DSC04999.JPG



PHOTO RW.2: Looking south at retaining wall.



File: DSC05000.JPG



PHOTO RW.3: Looking west along path at retaining wall.

RW.3

File: DSC04998.JPG

RETAINING WALL



PHOTO RW.4: Typical horizontal cracks with efflorescence throughout cap.



File: DSC04985.JPG



PHOTO RW.5: Typical spall at a vertical construction joint. Location show 240' from west end of wall.



File: DSC04991.JPG



PHOTO RW.6: Moderate efflorescence located 55' from west end of the wall.



File: DSC04992.JPG

WEST PIER



PHOTO WP.1: West Elevation looking east.



File: DSC05173.JPG



PHOTO WP.2: East Elevation looking southwest.



File: DSC05144.JPG



PHOTO WP.3: General view of wedge bearings.



File: DSC05157.JPG

PHOTOGRAPHS WEST PIER



PHOTO WP.4: Looking south at wedge bearing pedestal.



File: DSC05158.JPG



PHOTO WP.5: Looking east at approach span bearings.



File: DSC05162.JPG



PHOTO WP.6: Close up view showing overall good condition of masonry.



File: DSC05161.JPG

CENTER PIER

INSPECTION REPORT



PHOTO CP.1: East Elevation looking west.

CP.1

File: DSC05181.JPG



PHOTO CP.2: South Elevation looking north.

CP.2

File: DSC05050.JPG



PHOTO CP.3: General view looking southwest.

CP.3

File: DSC05052.JPG

Grays Ferry Pedestrian Bridge over Schuylkill River Concept Design Services

PHOTOGRAPHS EAST PIER



PHOTO EP.1: West Elevation looking east.

EP.1

File: DSC05130.JPG



PHOTO EP.2: East Elevation looking west.

EP.2

File: DSC05008.JPG



PHOTO EP.3: General view looking west at south nose.

EP.3

File: DSC05009.JPG

EAST PIER



PHOTO EP.4: Looking at wedge bearings.



File: DSC05178.JPG



PHOTO EP.5: Two stones below south wedge bearing shifted.
Vegetation present in the joints.



File: DSC05179.JPG



PHOTO EP.6: Triangular piece of capstone at south end shifted due to vegetation growth in joint.

EP.6

File: DSC05177.JPG